

Work Order Cost Summary

Work Order	Asset Number	Origination Date	Completion Date	Status	Actual Hours	C O S T S
C269833	RWY-0028L RUNWAY, 28L (10R)	01/25/2016	02/03/2016	CLO	96.00	Labor Cost: \$4,026.35 Material Cost: \$7,257.75 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$11,284.10
<u>Work Requested:</u>						
MR2016-308594 THREE LONG (APPROX. 50 + FT) LINEAR DISTORTION CRACKS OBSERVED AROUND THE CENTERLINE OF RWY 10R/28L EAST OF TWY T UP TO TWY E, FOD IS BEING RELEASED BY THESE CRACKS. CRACK SEALING OR RESURFACING IS NEEDED TO PREVENT FURTHER FAILURE AND FOD RELEASE.						
SEE ATTACHED.						
COMPLETED AS PER REQUEST.						
C270272	RWY-0028L RUNWAY, 28L (10R)	02/10/2016	02/24/2016	CLO	158.00	Labor Cost: \$6,773.27 Material Cost: \$15,532.40 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$22,305.67
<u>Work Requested:</u>						
MR2016-316397 REPAIR RAVELING AND ALLIGATOR CRACKING ALONG ASPHALT SEAMS ON RWY 28L AT INTERSECTION OF TWY D. SEE PICTURES.						
WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINTERS, PLEASE COORDINATE.						
PAVED ALLIGATOR CRACKING ON THE RWY.						
C270774	RWY-0028L RUNWAY, 28L (10R)	02/29/2016	03/18/2016	CLO	80.00	Labor Cost: \$3,377.97 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$3,377.97
<u>Work Requested:</u>						
MR2016-321084 REPAIR MODERATE RAVELING AND CRACKS AT INTERSECTION OF RWY 28L AND TWY Q (SOUTH SIDE OF RWY CENTERLINE, NORTH OF TWY Q HOLDBAR). SEE PHOTOS. THERE IS ALSO MODERATE CRACKING ALONG THE RWY EDGELINE (SOUTH OF CENTERLINE AT INTERSECTION OF TWY Q).						
WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINTERS. PLEASE COORDINATE.						
COMPLETED AS PER REQUEST.						
C271033	RWY-0001R RUNWAY, 01R (19L)	03/08/2016	06/13/2016	CLO	32.00	Labor Cost: \$1,287.00 Material Cost: \$336.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$1,623.00
<u>Work Requested:</u>						
MR2016-324341 SEVERE RAVELING AND MODERATE JOINT CRACKING ON RWY 1R BETWEEN TWY F AND RWY 28L.						
SEE ATTACHED.						
CRACK SEALED CRACKS ON RUNWAY.						
C271045	RWY-0001L RUNWAY, 01L (19R)	03/08/2016	04/29/2016	CLO	152.00	Labor Cost: \$5,672.74 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$5,672.74
<u>Work Requested:</u>						
MR2016-324340 LARGE / LONG CRACKS ALONG JOINTS ON RWY 19R NORTH OF 28R NEAR INTERSECTIONS OF TWY C AND TWY V. HOLES ARE FORMING IN VARIOUS LOCATIONS ALONG CRACKS. REQUIRES SEALANT ASAP. SEE PHOTOS.						
COMPLETED AS PER REQUEST. CRACK SEALING.						

Work Order Cost Summary

Work Order	Asset Number	Origination Date	Completion Date	Status	Actual Hours	C O S T S
C271192	RWY-0028L RUNWAY, 28L (10R)	03/14/2016	05/25/2016	CLO	172.00	Labor Cost: \$7,555.61 Material Cost: \$9,024.30 CONTRACT: \$0.00 OTHER: \$0.00 <hr/> TOTAL: \$16,579.91
<u>Work Requested:</u>						
MR2016-329228 10R / 28L RUTTING ADJACENT TO CENTER LINE. SEVERAL 1.5 TO 2-INCH CRACKS OBSERVED SOUTH OF RWY 10R CENTER LINE, BETWEEN TWY K AND Q. SEE ATTACHED.						
WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINT SHOP. PLEASE COORDINATE. COMPLETED AS PER REQUEST.						
C271433	RWY-0028L RUNWAY, 28L (10R)	03/21/2016	03/23/2016	CLO	72.00	Labor Cost: \$3,100.68 Material Cost: \$4,566.20 CONTRACT: \$0.00 OTHER: \$0.00 <hr/> TOTAL: \$7,666.88
<u>Work Requested:</u>						
MR2016-331615 CRACKING OBSERVED AT INTERSECTION OF RWY 28L AND 1R. THE CRACK, SITUATED WITHIN A PATCH LESS THAN A YEAR OLD, IS NORTH OF RUNWAY 28L CENTERLINE AND WITHIN THE RSA ENVIRONMENT OF 1R. THE CRACK COULD NOT BE MARKED WITH SAFETY PAINT DUE TO RAIN. SEE ATTACHED.						
WORK ORDERS ISSUED TO PAVING AND GROUNDS AND PAINT SHOP. PLEASE COORDINATE. COMPLETED AS PER REQUEST. PAVED 3 SPOTS						
C272030	RWY-0001L RUNWAY, 01L (19R)	04/13/2016	04/22/2016	CLO	0.00	Labor Cost: \$0.00 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 <hr/> TOTAL: \$0.00
<u>Work Requested:</u>						
MR2016-336903 LARGE / DEEP HOLES FORMING ALONG LONG CRACK ON RWY 1L, JUST NORTH OF TWY C, EAST OF RWY CENTERLINE. SEE PHOTOS.						
WORK ORDERS ISSUED TO PAVING AND GROUNDS AND PAINTERS. PLEASE COORDINATE. CANCEL, WORK WILL BE DONE ON ANOTHER WORK ORDER.						
C272154	RWY-0001L RUNWAY, 01L (19R)	04/18/2016	04/29/2016	CLO	0.00	Labor Cost: \$0.00 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 <hr/> TOTAL: \$0.00
<u>Work Requested:</u>						
MR2016-341524 LONG, DEEP CRACK ON RWY 01L BETWEEN THE 28's, EAST OF THE CENTERLINE (IT IS IN THE RSA OF 28L). THE CRACK IS AROUND 1-2 INCHES WIDE AND 1-2 INCHES DEEP IN SOME AREAS AND IS THROWING ROCKS. SEE PHOTOS.						
WORK ORDERS ISSUED TO PAVING AND GROUNDS AND PAINT SHOP. PLEASE COORDINATE. JOB COMPLETED ON C271045.						
C273380	RWY-0028L RUNWAY, 28L (10R)	06/06/2016	06/14/2016	CLO	88.00	Labor Cost: \$3,855.02 Material Cost: \$5,707.75 CONTRACT: \$0.00 OTHER: \$0.00 <hr/> TOTAL: \$9,562.77
<u>Work Requested:</u>						
MR2016-354909 POTHOLE AND MULTIPLE CRACKS ARE STARTING TO THROW ROCKS ON RWY 28L AT INTERSECTION OF TWY D AND TWY T. SEE PHOTOS. POTHOLE MARKED WITH ORANGE PAINT.						
WORK ORDERS ISSUED TO PAVING & GROUNDS & PAINTERS. PLEASE COORDINATE. COMPLETED AS PER REQUEST.						

Work Order Cost Summary

Work Order	Asset Number	Origination Date	Completion Date	Status	Actual Hours	C O S T S
C273418	RWY-0028R RUNWAY, 28R (10L)	06/08/2016	01/05/2017	CLO	0.00	Labor Cost: \$0.00 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$0.00

Work Requested:

MR2016-358764
 ASPHALT LIP FOR AN ELECTRICAL VAULT WITHIN IN THE RWY 28R RSA IS GREATER THAN 3". SEE PHOTOS.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINTERS, PLEASE COORDINATE.

CLOSED - PER NEW PROCUEDRES, OLDER THAN 6 MONTHS. APPROVED BY P. ACTON.

C273658	RWY-0028L RUNWAY, 28L (10R)	06/16/2016	07/05/2016	CLO	64.00	Labor Cost: \$2,597.23 Material Cost: \$1,204.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$3,801.23
---------	--------------------------------	------------	------------	-----	-------	--

Work Requested:

MR2016-359718

CRACKS AND LARGE HOLES FORMING ALONG ASPHALT JOINTS ON RWY 28L / 10R. LONG SECTION OF CRACKS / HOLES ON SOUTH SIDE OF CENTERLINE EXTENDING FROM TWY K INTERSECTION WEST BOUND. MORE CRACKS AND HOLES ON NORTH SIDE OF CENTERLINE JUST EAST OF TWY D/T INTERSECTION. BOTH SECTIONS ARE MARKED IN ORANGE PAINT.

NOTE: ATTACHED PICTURES ARE OF SECTION NEAR TWY K INTERSECTION ONLY; DID NOT HAVE TIME TO TAKE PICTURES OF AREA EAST OF TWY D/T.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINTERS. PLEASE COORDINATE.

CRACK SEALED 28L FROM TWY D TO TWY U.

C275075	RWY-0001L RUNWAY, 01L (19R)	08/10/2016	09/21/2016	CLO	0.00	Labor Cost: \$0.00 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$0.00
---------	--------------------------------	------------	------------	-----	------	--

Work Requested:

MR2016-378601
 REPAIR RAVELING AND AGGREGATE LOSS OBSERVED ON RWY 1L NORTH OF TWY G INTERSECTION ALONG RIGHT MAIN GEAR TRACK. SMALL POTHOLE DEVELOPED ALONG PATCH JOINT AND NEEDS TO BE MONITORED FOR WORSENING. SEE PICTURES.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINTERS. PLEASE COORDINATE.

COMPLETED WITH C275543.

C275543	RWY-0001L RUNWAY, 01L (19R)	08/26/2016	09/21/2016	CLO	88.00	Labor Cost: \$3,844.46 Material Cost: \$3,791.20 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$7,635.66
---------	--------------------------------	------------	------------	-----	-------	--

Work Requested:

MR2016-378601
 REPAIR RAVELING AND AGGREGATE LOSS OBSERVED ON TWY 1L NORTH OF TWY G INTERSECTION ALONG RIGHT MAIN GEAR TRACK. SMALL POTHOLE DEVELOPED ALONG PATCH JOINT AND NEEDS TO BE MONITORED FOR WORSENING. SEE PICTURES.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINTERS. PLEASE COORDINATE.

COMPLETED AS REQUESTED.

Work Order Cost Summary

Work Order	Asset Number	Origination Date	Completion Date	Status	Actual Hours	C O S T S
C275707	RWY-0028L RUNWAY, 28L (10R)	08/31/2016	12/05/2016	CLO	20.00	Labor Cost: \$764.76 Material Cost: \$280.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$1,044.76
<u>Work Requested:</u>						
MR2016-388237 REPAIR POTHOLE FORMING ALONG THE TWY D SOUTH EXIT LEAD-OFF LINE ON RWY 28L. THE POTHOLE IS APPROXIMATELY 1.5FT. LONG BY 1.5 INCHES DEEP. THE KERF WAS OBSERVED BROKEN AT EITHER END OF THE POTHOLE BUT HAS REMAINED INTACT. MONITOR THIS ISSUE UNTIL IT CAN BE REPAIRED BY P&G. SEE PICTURES.						
WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINTERS. PLEASE COORDINATE. CRACK SEAL KERF & CRACKED AREAS.						
C275735	RWY-0028R RUNWAY, 28R (10L)	08/31/2016	10/21/2016	CLO	919.00	Labor Cost: \$39,704.41 Material Cost: \$46,786.50 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$86,490.91
<u>Work Requested:</u>						
MR2016-388101 BASED ON OUR RWY 28R INSPECTION, PERFORM WORK AS FOLLOWS: 1. GRIND AND PAVE TWY T SOUTH HOLD BAR @ RWY 28R. EXISTING KERF ABOUT TO FAIL. REMOVE AND REINSTALL KERF. 2. GRIND AND PAVE TWO AREAS BETWEEN RWY 28R AND TWY E SOUTH HOLD BAR. 3. GRIND AND PAVE THREE AREAS SOUTH OF RWY 28R CENTER LINE BETWEEN TWY'S P & L. 4. GRIND AND PAVE TWY P SOUTH HOLD BAR @ RWY 28R. REMOVE & REINSTALL KERF. 5. GRIND AND PAVE TO REMOVE AND REINSTALL LIGHT AT TWY W NORTH OF TWY 28R. 6. GRIND AND PAVE BEHIND RWY 28R APPROACH LIGHTS.						
WORK ORDERS ISSUED TO ASPHALT CREW, LABORERS, ELECTRICIANS, AND PAINTERS. PLEASE COORDINATE. SEE ATTACHED. COMPLETED AS PER REQUEST.						
C275713	RWY-0028L RUNWAY, 28L (10R)	08/31/2016	09/14/2016	CLO	0.00	Labor Cost: \$0.00 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$0.00
<u>Work Requested:</u>						
MR2016-386400 REPAIR PAVEMENT RAVELING, POSSIBLY DUE TO PREVIOUS NIGHT'S POWER WASHING (TO REMOVE OLD PAINT MARKINGS). LOCATED ON HOLD BAR BETWEEN RWY 28L AND TWY B. CONDITION IS WORSE ON THE EAST AND WEST EDGE OF THE TAXIWAY. SEE PICTURES.						
WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINTERS. PLEASE COORDINATE. CANCELED BY OPS.						
C277478	RWY-0001R RUNWAY, 01R (19L)	11/02/2016	11/29/2016	CLO	401.00	Labor Cost: \$18,612.76 Material Cost: \$25,567.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$44,179.76
<u>Work Requested:</u>						
MR2016-411743 REPAIR ASPHALT DEPRESSION ON RWY 1R IN THE MAIN GEAR TRACK ABEAM TWY G. TWO SEPARATE PILOTS REPORTED BUMPS ON THE RUNWAY. SEE PICTURES.						
WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINTERS. PLEASE COORDINATE. COMPLETED AS PER REQUEST.						

Work Order Cost Summary

Work Order	Asset Number	Origination Date	Completion Date	Status	Actual Hours	C O S T S
C278572	RWY-0001R RUNWAY, 01R (19L)	12/14/2016	12/19/2016	CLO	6.00	Labor Cost: \$227.69 Material Cost: \$140.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$367.69
<u>Work Requested:</u>						
MR2016-426425 POTHOLE FOUND ON RWY 19L-1R ABEAM TWY L. THE POTHOLE IS ABOUT 11" IN LENGTH, 2" WIDTH AND 1" DEPTH. IT IS CURRENTLY NOT THROWING ROCKS. THE POTHOLE IS IN BETWEEN RWY 19L DESIGNATOR; WEST OF THE RUNWAY CENTERLINE. SEE ATTACHED PHOTOS.						
WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINTERS. PLEASE COORDINATE. CRACK SEALED AREA.						
C278724	RWY-0028R RUNWAY, 28R (10L)	12/19/2016	12/29/2016	CLO	0.00	Labor Cost: \$0.00 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$0.00
<u>Work Requested:</u>						
MR2016-349291 REPAIR POTHOLE APPROXIMATELY 4" WIDE BY 7" LONG 3/4" DEEP ON RWY 28R LEFT OF CENTERLINE JUST EAST OF TWY N MARKED WITH ORANGE PAINT. SEE ATTACHED.						
WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINTERS. PLEASE COORDINATE. WORK DONE WITH C278479.						
C278718	RWY-0028L RUNWAY, 28L (10R)	12/19/2016	12/29/2016	CLO	0.00	Labor Cost: \$0.00 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$0.00
<u>Work Requested:</u>						
MR2016-427834 REPAIR POLISHED AGGREGATE BEGINNING TO BREAK UP IN VARIOUS SPOTS ON THE EAST END OF RWY 10R. THE ISSUE IS IN VARIOUS SPOTS 25 FEET ON EITHER SIDE OF THE CENTER LINE MARKED IN ORANGE PAINT FROM THE NUMBERS MOVING WESTWARD APPROXIMATELY 75 FEET. SEE ATTACHED.						
WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINTERS. PLEASE COORDINATE. WORK DONE WITH C278479.						
C278720	RWY-0001R RUNWAY, 01R (19L)	12/19/2016	12/27/2016	CLO	40.00	Labor Cost: \$1,535.25 Material Cost: \$560.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$2,095.25
<u>Work Requested:</u>						
MR2016-428372 ASPHALT ON RWY 1R SURROUNDING THE START OF KERF OF TWY G LEAD-ON/OFF LEADING TO BETWEEN THE 1'S IS ERODING AND THROWING STONES. THE AREA NEEDS CRACK SEALING OR A PATCH TO PREVENT BLOWOUT.						
SEE PICTURES.						
WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINTERS. PLEASE COORDINATE. CRACK SEAL AS NEEDED.						
C279443	RWY-0028R RUNWAY, 28R (10L)	01/13/2017	07/19/2017	CLO	184.00	Labor Cost: \$8,334.66 Material Cost: \$13,591.20 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$21,925.86
<u>Work Requested:</u>						
MR2017-439165 ALLIGATOR CRACKING AND MUD PUMPING HAS BEEN OBSERVED ON TWY 10L-28R AT TWY S3. THE AREA REQUIRES RESURFACING TO PREVENT PAVEMENT FAILURE. SEE PHOTOS.						
WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINT SHOP. CLOSED BY SCHEDULING - OLDER THAN 6 MONTHS. 7/19/17 WORK COMPLETED AS PER REQUEST.						

Work Order Cost Summary

Work Order	Asset Number	Origination Date	Completion Date	Status	Actual Hours	C O S T S
C279441	RWY-0028L RUNWAY, 28L (10R)	01/13/2017	01/25/2017	CLO	200.00	Labor Cost: \$8,478.10 Material Cost: \$8,524.30 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$17,002.40

Work Requested:

MR2017-439166
 AT RUNWAY INTERSECTION 28L AND 1L, ABEAM CLOSED EXIT TAXIWAY J, THERE ARE MULTIPLE AREAS OF SOIL PUSHING UP FROM ALLIGATOR CRACKS AND PATCH JOINTS. THE AREAS ARE NORTH AND SOUTH OF THE RUNWAY 28L CENTERLINE, WITH MODERATE ALLIGATOR CRACKING NORTH OF CENTERLINE. THE AREA NEEDS RESURFACING WITHIN DAYS TO PREVENT A BLOWOUT AND EMERGENCY CLOSURE OF RUNWAY 28L. SEE PICTURES.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINT SHOPS.
 COMPLETED AS REQUESTED.

C280303	RWY-0028L RUNWAY, 28L (10R)	02/09/2017	02/16/2017	CLO	0.00	Labor Cost: \$0.00 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$0.00
---------	--------------------------------	------------	------------	-----	------	--

Work Requested:

MR2017-449026
 MULTIPLE SMALL HOLES FOUND ON A PATCH NORTH CENTER LINE ON RWY 10R/28L BETWEEN TWY D AND E. SEE ATTACHED.

WORK ORDERS ISSUED TO PAVING AND GROUNDS AND PAINTERS. PLEASE COORDINATE.
 WORK DONE WITH C280449.

C280453	RWY-0001R RUNWAY, 01R (19L)	02/15/2017	02/16/2017	CLO	0.00	Labor Cost: \$0.00 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$0.00
---------	--------------------------------	------------	------------	-----	------	--

Work Requested:

MR2017-450994
 RWY 19L CRACKING AND RAVELING ALONG PAVEMENT SEAM EAST OF CENTERLINE FROM TWY V TO RWY 28R.

NOTE: NOT ALL AREAS WERE MARKED WITH PAINT. SEE ATTACHED.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINTERS.
 WORK DONE WITH C280449.

C280461	RWY-0028L RUNWAY, 28L (10R)	02/15/2017	02/16/2017	CLO	0.00	Labor Cost: \$0.00 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$0.00
---------	--------------------------------	------------	------------	-----	------	--

Work Requested:

MR2017-349633
 REPAIR SEVERAL VERY LONG CRACKS ALONG ASPHALT SEAMS ON NORTH SIDE OF RWY 28L/10R CENTERLINE, BETWEEN TWY'S Q AND D. PAVEMENT RAVELING AND POTHOLS FORMING ALONG CRACKS - NEEDS CRACK SEALING. SEE PHOTOS.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINTERS.
 WORK DONE WITH C280449.

C280467	RWY-0001R RUNWAY, 01R (19L)	02/15/2017	02/15/2017	CLO	0.00	Labor Cost: \$0.00 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$0.00
---------	--------------------------------	------------	------------	-----	------	--

Work Requested:

MR2017-449812
 REPAIR FOUR HOLES FOUND ON RWY 19L/1R BETWEEN TWY F1 AND TWY G ON EITHER SIDE OF THE CENTER LINE. HOLES ARE MARKED IN ORANGE. SEE ATTACHED.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINTERS.
 CANCEL.

Work Order Cost Summary

Work Order	Asset Number	Origination Date	Completion Date	Status	Actual Hours	C O S T S
C280497	RWY-0001R RUNWAY, 01R (19L)	02/16/2017	02/17/2017	CLO	0.00	Labor Cost: \$0.00 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$0.00

Work Requested:

MR2017-451738
REPAIR CRACKING IN MULTIPLE AREAS OBSERVED AT RWY INTERSECTIONS RWY 1R/19L & RWY 28L/10R. SEE ATTACHED.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINTERS.

WORK DONE W/O C280449.

C281141	RWY-0028L RUNWAY, 28L (10R)	03/09/2017	10/12/2017	CLO	0.00	Labor Cost: \$0.00 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$0.00
---------	--------------------------------	------------	------------	-----	------	--

Work Requested:

MR2017-459862
A LARGE POTHOLE WAS FOUND ON RWY 28L / 10R JUST NORTH OF THE CENTER LINE AND TO THE EAST OF RWY 01R / 19L. THE HOLE WAS APPROXIMATELY 26" IN DIAMETER AND 3" DEEP. HOLE WAS MARKED IN ORANGE. SEE PICTURES.

WORK ORDER ISSUED TO PAVING AND GROUNDS AND PAINTERS.

CLOSED BY SCHEDULING - OLDER THAN 6 MONTHS.

C281154	RWY-0028L RUNWAY, 28L (10R)	03/10/2017	10/12/2017	CLO	0.00	Labor Cost: \$0.00 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$0.00
---------	--------------------------------	------------	------------	-----	------	--

Work Requested:

MR2017-460390
REPAIR PAVEMENT CRACKING ON RWY 28L BETWEEN RWY 1R & RWY 1L.

SEE ATTACHED.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINTERS.

CLOSED BY SCHEDULING - OLDER THAN 6 MONTHS.

C281256	RWY-0028L RUNWAY, 28L (10R)	03/14/2017	03/20/2017	CLO	0.00	Labor Cost: \$0.00 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$0.00
---------	--------------------------------	------------	------------	-----	------	--

Work Requested:

MR2017-460670
REPAIR CRACKING ON RUNWAY 28L NORTH OF THE CENTERLINE AND JUST EAST OF TWY E. SEE ATTACHED.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINT SHOPS.

WORK COMPLETED WITH WORK 280813.

C281248	RWY-0028L RUNWAY, 28L (10R)	03/14/2017	03/20/2017	CLO	0.00	Labor Cost: \$0.00 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$0.00
---------	--------------------------------	------------	------------	-----	------	--

Work Requested:

MR2017-460665
RUNWAY 28L HAS SHOVLING TO THE NORTH SIDE OF THE CENTERLINE, JUST WEST OF THE INTERSECTION OF 1L. SEE ATTACHED.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINT SHOPS.

WORK COMPLETED WITH W/O C280813.

Work Order Cost Summary

Work Order	Asset Number	Origination Date	Completion Date	Status	Actual Hours	C O S T S
C281236	RWY-0028L RUNWAY, 28L (10R)	03/14/2017	03/20/2017	CLO	0.00	Labor Cost: \$0.00 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$0.00

Work Requested:

MR2017-457147
 RUTTING AND POT HOLE ARE FORMING (APPROX. 24" LENGTH AND 2" WIDE) ON RWY 28L/19R SOUTH OF THE CENTERLINE AND JUST EAST OF TWY Q. SPOT IS MARKED IN ORANGE. SEE ATTACHED.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINT SHOPS.

WORK COMPLETED WITH W/O 280813.

C281252	RWY-0001L RUNWAY, 01L (19R)	03/14/2017	03/20/2017	CLO	0.00	Labor Cost: \$0.00 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$0.00
---------	--------------------------------	------------	------------	-----	------	--

Work Requested:

MR2017-460660
 REPAIR POT HOLE FORMING AT THE INTERSECTION OF RUNWAY 1L AND RUNWAY 28L. IT IS IN THE WHEEL TRACK OF RUNWAY OF 1L. THERE IS ALSO A LOT OF CRACKING AROUND THE HOLE, IT MAY FAIL SOON. PER DANIEL LEE, REPAIR WILL BE DEFERRED UNTIL SUNDAY NIGHT. SEE ATTACHED.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINT SHOPS.

WORK COMPLETED WITH W/O 280813

C281336	RWY-0001L RUNWAY, 01L (19R)	03/16/2017	03/16/2017	CLO	203.50	Labor Cost: \$10,915.54 Material Cost: \$24,981.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$35,896.54
---------	--------------------------------	------------	------------	-----	--------	---

Work Requested:

- 1) AT RUNWAY 1L EMAS, TAXIWAY B SHOULDER & TAXIWAY A2 SHOULDER / HOLDBAR, GRIND AND PAVE EXISTING PAVEMENT TO IMPROVE AIRFIELD PONDING AREA. FINISHED GRADES SHOULD PROMOTE DRAINAGE TOWARDS THE NEAREST CATCH BASIN.
- 2) AT PLOT 40, NEAR FIRE HOUSE #2, RAISE EXISTING PAVEMENT TO CORRECT A LOW SPOT AND TO IMPROVE PONDING AREA. FINISHED GRADES SHOULD PROMOTE DRAINAGE TOWARDS TO THE NEAREST CATCH BASIN.

WORK COMPLETED PER REQUEST ON 3/11/17.

C282241	RWY-0001R RUNWAY, 01R (19L)	04/18/2017	07/07/2017	CNX	0.00	Labor Cost: \$0.00 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$0.00
---------	--------------------------------	------------	------------	-----	------	--

Work Requested:

MR2017-471408
 REPAIR RAVELING ON RWY 19L EAST OF THE CENTER LINE BETWEEN RWY 28R AND TWY C. SEE ATTACHED.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINT SHOPS.

CANCELLED WITHN W/O C284365.

C282843	RWY-0028L RUNWAY, 28L (10R)	05/08/2017	08/14/2017	CLO	24.00	Labor Cost: \$938.12 Material Cost: \$224.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$1,162.12
---------	--------------------------------	------------	------------	-----	-------	--

Work Requested:

MR2017-481066
 M223 OBSERVED RUTTING AROUND TWY CENTERLINE LIGHTS ON THE SOUTHSIDE OF RWY 28L/10R AT TWY D NORTH OF THE HOLD BAR. KERFING ALSO NEEDS TO BE FILLED IN.

WORK ORDERS ISSUED TO PAVING AND GROUNDS AND PAINTERS. PLEASE COORDINATE.

SEE ATTACHED.

WORK COMPLETED.

Work Order Cost Summary

Work Order	Asset Number	Origination Date	Completion Date	Status	Actual Hours	C O S T S
C285233	RWY-0028L RUNWAY, 28L (10R)	08/03/2017	08/17/2017	CLO	8.00	Labor Cost: \$294.80 Material Cost: \$36.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$330.80

Work Requested:

MR2017-515963
 ASPHALT AND FILL AROUND "FAA-MALS R5" HAS WASHED OUT AND APPEARS TO HAVE CAUSED A DEEP GAP OVER 12" DEEP AND 3" WIDE. LOCATED AT THE EAST END OF RWY 10R/28L ABOUT 4' FROM THE WATER PERIMETER VSR.

SEE ATTACHED.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINT SHOPS.

FILL VOID AROUND "FAA MAL R5" WITH CONCRETE.

C286734	RWY-0028R RUNWAY, 28R (10L)	09/27/2017	10/02/2017	CLO	120.00	Labor Cost: \$4,879.07 Material Cost: \$2,940.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$7,819.07
---------	--------------------------------	------------	------------	-----	--------	--

Work Requested:

MR2017-526234
 ON 10/2/17 CRACK SEAL ON RWY 28R / 10L.

KEVIN ALLEN HAS DETAILS.

WORK ORDERS ISSUED TO PAVING AND GROUNDS AND PAINTERS.

WORK COMPLETED AS PER REQUEST.

C288092	RWY-0001L RUNWAY, 01L (19R)	11/21/2017	12/04/2017	CLO	40.00	Labor Cost: \$1,575.46 Material Cost: \$700.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$2,275.46
---------	--------------------------------	------------	------------	-----	-------	--

Work Requested:

MR2017-557801
 AT RWY 1L-19R, REPAIR SEAM SEPARATION APPROXIMATELY 1" WIDE AND 5" BETWEEN F AND F1.

WORK ORDERS ISSUED TO PAVING & D GROUNDS AND PAINTERS. PLEASE COORDINATE.

WORK COMPLETED AS PER REQUEST.

C289764	RWY-0028L RUNWAY, 28L (10R)	02/02/2018	02/14/2018	CLO	264.00	Labor Cost: \$13,149.42 Material Cost: \$9,809.30 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$22,958.72
---------	--------------------------------	------------	------------	-----	--------	--

Work Requested:

MR2018-584657
 @ RWY 28L-10R BETWEEN RWY 01'S, REPAIR ADDITIONAL RAVELING ON RWY 28L INTO THE RSA OF RWY 01R.

SEE ATTACHED.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINTERS.

WORK COMPLETED PER REQUEST.

Work Order Cost Summary

Work Order	Asset Number	Origination Date	Completion Date	Status	Actual Hours	C O S T S
C290039	RWY-0028L RUNWAY, 28L (10R)	02/12/2018	02/14/2018	CLO	0.00	Labor Cost: \$0.00 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$0.00

Work Requested:

MR2018-585143
 PREVIOUS PAVEMENT REPAIRS AND PATCHES ON RWY 28L/10R ARE RAVELING, THROWING ROCKS, AND APPEAR TO BE DETERIORATING RAPIDLY. MULTIPLE AREAS OF MISSING AGGREGATE WERE FOUND RANGING FROM 1 TO 4 INCHES AND APPROXIMATELY 1 YO 2 INCHES DEEP. THE LOCATION OF THE ANOMALIES ARE NORTH OF THE RUNWAY CENTERLINE BETWEEN RWY 1L AND RWY 1R, ABEAM THE VOR AND ABEAM THE 6,000 FT. RDR MARKER, IN THE RECENTLY REPAIRED PAVEMENT. ANOMALIES WERE FOUNDED BY M210 DURING ROUTINE RUNWAY INSPECTION WHERE A 2 INCH BY 2 INCH AGGEGATE OF PAVEMENT WAS RECOVERED.

SEE ATTACHED PICTURES.

WORK ORDERS ISSUED TO PAVING AND GROUNDS AND PAINTERS. PLEASE COORDINATE.

CLOSED WITH W/O 289764.

C290188	RWY-0001L RUNWAY, 01L (19R)	02/20/2018	03/19/2018	CLO	48.00	Labor Cost: \$1,953.78 Material Cost: \$560.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$2,513.78
---------	--------------------------------	------------	------------	-----	-------	--

Work Requested:

MR2018-585030
 REPAIR CRACKING APPROXIMATELY 5' EAST OF THE RWY 19R CENTERLINE BETWEEN TWYS F1 AND G. THE CRACKING IS IN THE PATCHES AND IS SPREAD OUT FOR MOST OF THE DISTANCE BETWEEN TWYS F1 AND G. SEE ATTACHED.

*2/10/18 - CONDITON UNCHANGED; UPDATED DATA POINT ON AIRS MAP TO REFLECT LINEAR CONDITON.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINT SHOPS.

WORK COMPLETED.

C291110	RWY-0001R RUNWAY, 01R (19L)	03/26/2018	04/23/2018	CLO	72.00	Labor Cost: \$3,280.64 Material Cost: \$4,160.20 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$7,440.84
---------	--------------------------------	------------	------------	-----	-------	--

Work Requested:

MR2018-592992
 AT RWY 1R/19L EAST AND WEST OF THE CENTERLINE, BETWEEN TWY C AND RWY 28R AREA STARTING TO SHOW SIGNS OF POTHOLES BEGINNING TO FORM. AREA SHOULD BE WATCHED FOR FURTHER DETERIORATION OF SURFACE.

WORK ORDERS ISSUED TO PAVING AND GROUNDS AND PAINTERS. PLEASE COORDINATE.

SEE ATTACHED.

WORK COMPLETED AS PER REQUEST.

C291407	RWY-0001L RUNWAY, 01L (19R)	04/09/2018	04/09/2018	CLO	86.00	Labor Cost: \$3,850.86 Material Cost: \$4,077.10 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$7,927.96
---------	--------------------------------	------------	------------	-----	-------	--

Work Requested:

MR2018-607513
 ON THE HEAVY AIRCRAFT WHEEL TRACK ALONG TWY F ON RWY 1L THE PAVEMENT IS STARTING TO FAIL. THE AREA IS ON THE SOUTH SIDE OF THE TWY F CENTERLINE AND TO THE WEST OF RWY 1L CENTERLINE. THE PAVEMENT HAS CRACKING EXTENDING APPROXIMATELY 12 FEET ALONG THE WHEEL TRACK AND THERE APPEARS TO BE SOME DEPRESSIONS IN THE ASPHALT IN THE SAME AREA.

SEE ATTACHED.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINT SHOPS.

WORK COMPLETED PER REQUEST.

Work Order Cost Summary

Work Order	Asset Number	Origination Date	Completion Date	Status	Actual Hours	C O S T S
C291405	RWY-0028L RUNWAY, 28L (10R)	04/09/2018	04/09/2018	CLO	88.00	Labor Cost: \$4,037.26 Material Cost: \$3,846.10 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$7,883.36

Work Requested:

MR2018-607586
 THE EAST EDGE OF THE PATCH OF RWY 10R/28L BETWEEN THE INTERSECTION OF 19L AND 19R IS SPALLING. SEE ATTACHED.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINT SHOPS.

WORK COMPLETED PER REQUEST.

C291992	RWY-0028L RUNWAY, 28L (10R)	04/30/2018	05/01/2018	CLO	88.00	Labor Cost: \$3,876.22 Material Cost: \$4,083.20 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$7,959.42
---------	--------------------------------	------------	------------	-----	-------	--

Work Requested:

MR2018-617900
 AT NORTH OF RWY 28L CENTERLINE, BETWEEN RWY'S 1R AND 1L, SOUTH OF THE VOR (PRIOR MIDDLE REPAIR) PATCH APPEARED TO BE PUSHING AND CRACKING. NO DEBRIS OBSERVED ON THIS INSPECTION. MONITOR FOR POSSIBLE DEGRADATION.

WORK ORDERS ISSUED TO PAVING AND GROUNDS AND PAINTERS. PLEASE COORDINATE.

SEE ATTACHED.

THIRD TIME DOING THIS PATCH. WORK COMPLETED PER REQUEST.

C293443	RWY-0028L RUNWAY, 28L (10R)	06/25/2018	06/25/2018	CLO	24.00	Labor Cost: \$1,377.82 Material Cost: \$932.65 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$2,310.47
---------	--------------------------------	------------	------------	-----	-------	--

Work Requested:

MR2018-639109
 AT RWY 28L, NORTH OF CENTERLINE, BETWEEN RWYS 1R & 1L, ALLIGATOR CRACKING OBSERVED ON PRIOR CENTER PATCH REPAIRS, SOUTH OF THE VOR, AND ANOTHER ON THE EASTERN MOST PATCH. SEE ATTACHED.

WORK ORDERS ISSUED TO PAVING AND GROUNDS AND PAINTERS. PLEASE COORDINATE.

EMERGENCY ASPHALT REPAIR RWY 28L BTW RWY 1L / 1R.
 PATCH #3 = 14' X 10' AT 3" DEED, EAST SIDE OF PATCH 3RD TIME REPATCHING.
 PATCH #1 = 16' X 7' AT 3" DEEP, WEST SIDE OF PATCH 5TH TIME REPATCHING.

C293436	RWY-0028L RUNWAY, 28L (10R)	06/25/2018	06/26/2018	CLO	0.00	Labor Cost: \$0.00 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$0.00
---------	--------------------------------	------------	------------	-----	------	--

Work Requested:

EMER. REPAIR 28L- BETWEEN THE ONES.

CANCEL WORK ORDER FROM OPS FOR THIS WORK. SAME JOB C293443.

C293960	RWY-0028L RUNWAY, 28L (10R)	07/13/2018	07/13/2018	CLO	96.00	Labor Cost: \$4,468.11 Material Cost: \$4,020.65 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$8,488.76
---------	--------------------------------	------------	------------	-----	-------	--

Work Requested:

ANOMALY2018-678
 NORTH OF RWY 28L CENTERLINE, BETWEEN RWY'S 1R & 1L, SOUTH OF THE VOR (PRIOR MIDDLE REPAIR), GRIND AND PAVE PATCH THAT APPEARED TO BE PUSHING AND CRACKING. NO DEBRIS OBSERVED ON THIS INSPECTION. MONITOR FOR POSSIBLE DEGRADATION.

SEE ATTACHED.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINT SHOPS.

AS REQUESTED.

Work Order Cost Summary

Work Order	Asset Number	Origination Date	Completion Date	Status	Actual Hours	C O S T S
C294552	RWY-0001R RUNWAY, 01R (19L)	08/01/2018	08/08/2018	CLO	0.00	Labor Cost: \$0.00 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$0.00

Work Requested:

ANOMALY2018-1131
REPAIR DEPRESSION ON WEST SIDE HOLD BAR FOR RWY 1R/19L @ TWY M. IT IS APPROXIMATELY 3' IN DIAMETER ADJACENT TO CENTER LINE JUST SHORT OF THE HOLD BAR.

SEE ATTACHED.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINT SHOPS.

CLOSED WITH W/O 294554. JACK HAMMER OUT DEPRESSION IN ASPHALT 3'X3' X4" DEEP.

C294971	RWY-0001R RUNWAY, 01R (19L)	08/15/2018	08/16/2018	CLO	0.00	Labor Cost: \$0.00 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$0.00
---------	--------------------------------	------------	------------	-----	------	--

Work Requested:

ANOMALY2018-508 / AIRS635750
REPAIR MISSING KERF ALONG RWY 19L/1R C/L, JUST NORTH OF TWY G (APPROXIMATELY 4"x1").

SEE ATTACHED.

WORK ORDERS ISSUED TO PAVING & GROUNDS, ELECTRICIANS, AND PAINT SHOPS.

COMPLETED. WORK CLOSED WITH C294968.

C295317	RWY-0028L RUNWAY, 28L (10R)	08/27/2018	08/28/2018	CLO	80.00	Labor Cost: \$3,768.69 Material Cost: \$3,295.10 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$7,063.79
---------	--------------------------------	------------	------------	-----	-------	--

Work Requested:

ANOMALY2018-1659
REPAIR ASPHALT CRACKS AND RUTTING ON RWY 10R / 28L BETWEEN RWY 01L / 19R & 01R / 19L NORTH OF THE CENTERLINE MARKINGS. SEE ATTACHED.

WORK ORDERS ISSUED TO PAVING AND GROUNDS AND PAINTERS. PLEASE COORDINATE.

GRIND AND PAVE RUTTING AND CRACKS ON RWY 28L BETWEEN RWY 1L/1R. 6TH TIME FINNY SAVE PATCH, FAR WEST PATCH, NORHT OF CENTERLINE.

C295924	RWY-0001L RUNWAY, 01L (19R)	09/14/2018	09/19/2018	CLO	0.00	Labor Cost: \$0.00 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$0.00
---------	--------------------------------	------------	------------	-----	------	--

Work Requested:

ANOMALY2018-2039
REPAIR CRACKING AT THE RWY 1L CENTERLINE BETWEEN TWY H AND TWY G. C/L MARKING LOCATED NORTH OF H.

SEE ATTACHED.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINT SHOPS.

CANCEL WORK REQUEST TO MINOR FOR REPAIR.

C296172	RWY-0028L RUNWAY, 28L (10R)	09/24/2018	00/00/0000	IWM	0.00	Labor Cost: \$0.00 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$0.00
---------	--------------------------------	------------	------------	-----	------	--

Work Requested:

ANOMALY2018-2501
AT RWY 28L, PRIOR ASPHALT REPAIR PATCH (EASTERNMOST PATCH WEST OF RWY 1R) OBSERVED WITH NEW CRACKS. SEE ATTACHED PICS & MAP REFERENCE LOCATION. BETWEEN RUNWAYS 01L & 01R. M210. DRUING MY INSPECTION OF THE PATCH ON RWY 28L / 1R RSA PATCH, ADDITIONAL RUTTING AND PUSHING WAS NOTED ON THE MOST RECENT PATCH CLOSER RWY 1L. SEE ATTCHED PICTURES. M225; 9/24/18 0545.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINTERS. PLEASE COORDINATE.

Work Order Cost Summary

Work Order	Asset Number	Origination Date	Completion Date	Status	Actual Hours	C O S T S
C296477	RWY-0001R RUNWAY, 01R (19L)	10/03/2018	10/10/2018	CLO	156.00	Labor Cost: \$7,119.02 Material Cost: \$13,439.50 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$20,558.52

Work Requested:

ANOMALY2018-2560
EIGHT AREAS OF CRACKING RUNNING HORIZONTALLY ALONG THE WIDTH OF TAXI F1 AT RUNWAY 1R. THE CRACKING IS BETWEEN THE RUNWAY EDGE LINE MARKING AND THE HOLD BAR FOR RWY 1R. AREAS ARE MARKED WITH ORANGE PAINT.

WORK ORDERS ISSUED TO PAVING AND GROUNDS AND PAINT SHOPS.

SEE ATTACHED.

COMPLETED.

C296696	RWY-0001R RUNWAY, 01R (19L)	10/10/2018	10/30/2018	CLO	160.00	Labor Cost: \$7,259.65 Material Cost: \$12,082.60 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$19,342.25
---------	--------------------------------	------------	------------	-----	--------	--

Work Requested:

ANOMALY2018-2562
SEVERAL AREAS OF ALLIGATOR CRACKING ON RWY 1R ABEAM TWY F. ALSO CRACKING ALONG THE GROOVES AND SOME LOOSE STONE OBSERVED IN THE CRACKS. MARKED WITH PAINT.

WORK ORDERS ISSUED TO PAVING AND GROUNDS AND PAINTERS.

SEE ATTACHED.

GRIND AN PAVE THREE LOCATIONS ON RWY 1R @ TWY F.

C296898	RWY-0001R RUNWAY, 01R (19L)	10/17/2018	10/25/2018	CLO	152.00	Labor Cost: \$6,949.89 Material Cost: \$13,008.80 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$19,958.69
---------	--------------------------------	------------	------------	-----	--------	--

Work Requested:

ANOMALY2018-2586
REPAIR RUTTING ON THE WEST SIDE OF RWY 1R/19L FROM THE MANDATORY SURFACE PAINTED HOLD BAR ON TWY C EAST ONTO RWY 1R/19L.

SEE ATTACHED.

WORK ORDERS ISSUED TO PAVING AND GROUNDS, ELECTRICIANS, AND PAINTERS.

GRIND AND PAVE TWY C AT RWY 19L NORHT & SOUTH OF CENTERLINE 14'X136' @3" DEEP/
14'X173' @3" DEEP.

C297073	RWY-0001R RUNWAY, 01R (19L)	10/24/2018	10/31/2018	CLO	96.00	Labor Cost: \$4,468.11 Material Cost: \$7,944.40 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$12,412.51
---------	--------------------------------	------------	------------	-----	-------	---

Work Requested:

ANOMALY2018-2681
GRIND AND PAVE DEPRESSIONS AND DIVOTS ON RIGHT SIDE OF CENTERLINE ON RWY 1R ABEAM TWY L2.

SEE ATTACHED.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINT SHOPS.

GRIND AND PAVE RIPPLING ON RWY 1R AT TWY L2, 43'X10' / 33'X71' @3" DEEP.

Work Order Cost Summary

Work Order	Asset Number	Origination Date	Completion Date	Status	Actual Hours	C O S T S
C297758	RWY-0028L RUNWAY, 28L (10R)	11/19/2018	11/19/2018	CLO	16.00	Labor Cost: \$607.20 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$607.20

Work Requested:

ANOMALY2018-2852
 A PREVIOUS PATCH AROUND AN IN-GROUND RGL FOR RUNWAY 28L/10R IS DETERIORATING. THE RGL IS LOCATED ON THE SOUTH SIDE OF RWY 28L/10R AT THE INTERSECTION OF TWY E. GRIND AND PAVE.

SEE ATTACHED.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINT SHOPS.

REMOVE BROKEN ASPHALT AROUND KERF AND LIGHT, PATCH BACK WITH HOT ASPHALT 3'X3' @3" DEEP.

C298370	RWY-0001L RUNWAY, 01L (19R)	12/10/2018	12/14/2018	CLO	0.00	Labor Cost: \$0.00 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$0.00
---------	--------------------------------	------------	------------	-----	------	--

Work Requested:

ANOMALY2018-2765
 AIMING POINT WEST SIDE OF RWY 19L IS CHIPPING AWAY.

SEE ATTACHED.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINT SHOPS.

CANCEL, PAINTERS WORK ONLY.

C298756	RWY-0028R RUNWAY, 28R (10L)	12/20/2018	00/00/0000	IWM	0.00	Labor Cost: \$0.00 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$0.00
---------	--------------------------------	------------	------------	-----	------	--

Work Requested:

ANOMALY2018-3112
 REPAIR APPROXIMATELY 3" ROUND BY 1" DEEP HOLE ON THE CENTERLINE OF RWY 10L/28R ABEAM TWY T.

SEE ATTACHED.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINT SHOPS.

C298965	RWY-0001L RUNWAY, 01L (19R)	12/31/2018	00/00/0000	IWM	0.00	Labor Cost: \$0.00 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$0.00
---------	--------------------------------	------------	------------	-----	------	--

Work Requested:

ANOMALY2018-3079
 LOTS OF CRACKS ARE STARTING TO RAVEL AND DEVELOP HOLES ON RWY 01L, BOTH SIDES OF THE CENTERLINE, BETWEEN RWY 28L AND TWY F1.

SEE PHOTOS.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINT SHOPS.

Work Order Cost Summary

Work Order	Asset Number	Origination Date	Completion Date	Status	Actual Hours	C O S T S
C299012	RWY-0028L RUNWAY, 28L (10R)	01/02/2019	00/00/0000	IWM	0.00	Labor Cost: \$0.00 Material Cost: \$0.00 CONTRACT: \$0.00 OTHER: \$0.00 TOTAL: \$0.00

Work Requested:

ANOMALY2019-588/AIRS601414
 PLEASE CRACK SEAL THE ASPHALT JOINTS ON RWY 28L. THERE ARE MULTIPLE LOCATIONS WHERE IT APPEARS AGGREGATE HAS COME LOOSE IN THE JOINTS, ESPECIALLY BETWEEN RWY1L AND WEST END. THE AREA EAST OF TWY P IS NOT AS NOTICEABLE DUE TO RUBBER DEPOSITS IN THE TDZ.

WORK ORDERS ISSUED TO PAVING & GROUNDS AND PAINT SHOPS.

R E P O R T T O T A L S	
ACTUAL HOURS:	4593.50
LABOR:	\$204,517.62
MATERIAL:	\$253,009.20
CONTRACT:	\$0.00
OTHER:	\$0.00
GRAND TOTAL:	\$457,526.82

65 Work Order(s) listed.