

Community Development Services 400 South Vine Street Urbana, IL 61 801 (217) 384-2444 FAX (217) 384-0200

October 19, 2011

Alpha Omicron Pi ATTN: Marla Hutcherson 706 S. Mathews Urbana, IL 61801

RE:

706 S. Mathews

PI:

93-21-18-254-002

Dear Ms. Hutcherson:

During a reinspection of the subject property on October 18, 2011, we noted that the violations from our certified housing inspections have been corrected.

Thank you for the cooperation you have shown in protecting the health, safety, and general welfare of the public by upholding the minimum property standards adopted by our City and the University of Illinois.

www.city.urbana.il.us

Sincerely,

Clay R. Baier

Housing Inspector

(217)384-2436 or FAX(217)384-0200

CRB:vpp

CC:

Mari Anne Brocker



URBANA COMMUNITY DEVELOPMENT SERVICES DEPARTMENT HOUSING, INSPECTION - (217) 384-2436 or (217) 328-8274 LIFE SAFETY 1 The exit light(s) located shall be illuminated at all times. The exit located shall have a clear access. The emergency lighting unit located at Chartel from , hallway 3 shall be repaired or replaced. Fire or smoke door(s) located at shall not be blocked open. 5. Repair or replace panic hardware located at 6. Exit(s) located at shall not be locked or barred. Repair the exit door located at \_\_\_\_\_\_. Hard to open, broken, or blocked. FIRE PROTECTION SYSTEMS 8 \_\_\_\_ The extinguisher(s) located at \_\_\_\_\_ are due for annual inspection. The hood extinguishing system is due for semi-annual inspection. 9 The fire alarm system (location & problem) \_\_\_\_\_ The heat/smoke detector located at 11. shall be repaired. The carbon monoxide detector located shall be repaired. Fire alarm checked: Yes No 13. Fire Department key box: Yes No No Not Required ELECTRICAL \_\_\_\_\_ The receptacle/switch cover located at shall be installed The electrical service panel located at shall have clear access. Remove temporary wiring (extension cords) located at \_\_\_\_ 17. 18. Replace broken receptacle, switch, or circuit breaker located at 19. Repair or replace worn or broken electrical wiring or plug located at PROPERTY MAINTENANCE 20. \_\_\_\_\_ Ceiling tile(s) shall be replaced, located at \_\_\_ Repair the holes in the walls, ceiling, floor, etc., located at \_\_\_\_ All flammable or combustible liquids shall be kept in approved safety containers. 23. Gasoline-powered equipment stored at Remove excessive accumulation of rubbish located at \_\_\_\_ 25. \_\_\_\_ The Boiler Certificate is expired. U OF I HOUSING STANDARDS Room(s) are extremely tidy. lack responsible housekeeping Room(s) Hot plates, electric skillets, or toaster in room(s) must be removed. This housing inspection was made of the above referenced occupancy for the purpose of protecting the health, safety, and general welfare and correcting conditions which may tend to cause or contribute to a situation which must be corrected in order to bring the conditions up to the minimum standards prescribed by the proper codes. A follow-up inspection will be made on Owner/Agent (Please Print)

Number of Occupants