

**From:** [isaac](#)  
**To:** [Isaias Ramirez](#)  
**Cc:** [Gerry Gonzales](#)  
**Subject:** Estimate #2351  
**Date:** Tuesday, April 4, 2023 12:38:13 PM  
**Attachments:** [2351-Parks-Recreation-Department.pdf](#)

---

**CAUTION:** External Email. Proceed Responsibly.

Dear Customer,

Please find the attached estimate.

Thank you!

# ESTIMATE



DECADENZA

**DECADENZA INC.**

16321 WILTON PLACE  
 TORRANCE, CA 90504  
 Vendor#195138

**BILL TO**

Parks & Recreation Department  
 Accounting Section  
 1000 South Fremont Street  
 Unit #40  
 Alhambra, CA 91803

**SHIP TO**

Parks & Recreation Department  
 East Region Warehouse  
 267 Cloverleaf Drive  
 Baldwin Park, CA 91706

**ESTIMATE #**

2351

**ESTIMATE DATE**

04/04/2023



QTY	DESCRIPTION	UNIT PRICE	AMOUNT
1	Lead Screw Nut For Sp Unit	108.00	108.00
2	Lead Screw Bushing For Sp/Ecf	43.00	86.00
1	Lead Screw Bush Segment	136.00	136.00
1	UV Lamp For Sp-25-4, Sp-25-4S, Sp-25-6, and Sp-25-8	1,105.00	1,105.00
1	Quartz Thimble for Sp-25-4, Sp-25-4S & Sp-25-6	974.00	974.00
1	Quad Ring Seal Kit for Sp-13-4, Sp-25-4 and Sp-25-4S	266.00	266.00
1	Anode 3/8" x 3" x 1/2" for Eco-110-4 and Etc-113-5	50.00	50.00
1	304SS FxF Pipe Adapter, 1/2"x 3/4"	53.00	53.00
1	Labor: Atlantic Park Splash Pad ETS Service Isolated the UV Chamber and remove the lamp, quartz sleeve, and wiper assembly. Replace O-Rings and seals on the wire assembly and end plates. Re-Install the wiper Assembly, new quartz sleeves, and anode. Apply water to the Chamber and check for leaks. Install lamps, turn on the unit, clear alarms, and calibrate the wiper board. Check programming and adjust the UV monitor.	2,699.00	2,699.00
Subtotal			5,477.00

9.5%

263.92

**TOTAL**

**\$5,740.92**

*Thank you*

**TERMS & CONDITIONS**

THANK YOU FOR YOUR BUSINESS

