

## Work Order Directory

Ordered by: WO#

Property=.ph AND Call Dates=07/01/2013-11/30/2013 AND Scheduled Dates=07/01/2013-11/30/2013 AND Completion Dates=07/01/2013-11/30/2013

WO#	Prop-Unit	Status	Category	Brief Desc	Call Date	Schedule Date	Complete Date	Vendor	Amount
100	hacienda-HA513	Work Complete	OTHER	HA513 vacant	07/10/2013	07/10/2013	08/08/2013	v0003246 - STRONGBUILT CONSTRUCTION	240.55
101	nystrom-NV121	Work Complete	PLUMBING	1324 Maine stoppage	07/10/2013	07/10/2013	07/10/2013	v0002938 - PREFERRED PLUMBING & DRA	0
102	hacienda-HA220	Work Complete	OTHER	HA220 vacant	07/10/2013	07/10/2013	08/08/2013	v0003246 - STRONGBUILT CONSTRUCTION	388.46
103	hacienda-HA209	Work Complete		HA209 vacant	07/10/2013	07/10/2013	08/08/2013	v0003246 - STRONGBUILT CONSTRUCTION	151.83
104	hacienda-HA326	Work Complete	OTHER	HA326 vacant	07/10/2013	07/10/2013	08/08/2013	v0003250 - MICHAEL'S FLR COV/MJ8 GEN	398.94
105	hacienda-HA109	Work Complete	SERVICE	HA109 lock	07/10/2013	07/11/2013	07/11/2013	v0002935 - B&B LOCKMSMITH	0
112	nystrom-NV169	Work Complete	OTHER	250 MWS window	07/11/2013	07/12/2013	07/12/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
113	friend-	Work Complete	OTHER	FM lock box	07/12/2013	07/12/2013	07/13/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
114	hacienda-	Work Complete	PLUMBING	HA flooding	07/12/2013	07/12/2013	07/12/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
116	friend-FM238	Work Complete	PLUMBING	546 Stege Disposal	07/12/2013	09/10/2013	09/19/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
119	nystrom-NV101	Work Complete	PLUMBING	350 13th Heater	07/15/2013	07/16/2013	07/19/2013	v0003283 - OAKLAND CONSTRUCTION GR	8.36
121	friend-FM227	Work Complete	PLUMBING	609 S37th stoppage	07/15/2013	07/16/2013	08/24/2013	v0002938 - PREFERRED PLUMBING & DRA	0
124	hacienda-HA301	Work Complete	SERVICE	HA301 lock	07/15/2013	07/15/2013	07/15/2013	v0002935 - B&B LOCKMSMITH	0
127	triangle-TC22	Work Complete	OTHER	938 8 vacant	07/16/2013	07/16/2013	09/30/2013	v0003283 - OAKLAND CONSTRUCTION GR	914.55
128	nystrom-NV184	Work Complete	OTHER	1517 vacant	07/16/2013	07/16/2013	08/08/2013	v0003237 - ALPHA DESIGN PLANNING/CO	623.15
129	nystrom-NV162	Work Complete	OTHER	220 MWS vacant	07/16/2013	07/16/2013	07/19/2013	v0003237 - ALPHA DESIGN PLANNING/CO	174.34
131	hacienda-HA414	Work Complete	SERVICE	HA414 Broken Window	07/16/2013	07/16/2013	07/16/2013	v0003283 - OAKLAND CONSTRUCTION GR	0
132	nevin-NE421	Work Complete	PLUMBING	NE421 stoppage	07/16/2013	07/17/2013	07/17/2013	v0002938 - PREFERRED PLUMBING & DRA	0
133	triangle-TC84	Work Complete	SERVICE	974 TC glass	07/16/2013	07/16/2013	07/18/2013	v0002937 - ALL GLASS	0
143	friend-FM252	Work Complete	SERVICE	576 Stege lock	07/16/2013	07/18/2013	09/04/2013	v0002935 - B&B LOCKMSMITH	0
148	hacienda-HA206	Work Complete	PLUMBING	HA206 sink	07/17/2013	07/17/2013	07/17/2013	-	0
152	friend-FM215	Work Complete	OTHER	561 S37 head	07/17/2013	07/18/2013	07/24/2013	v0003246 - STRONGBUILT CONSTRUCTION	17.53
166	hacienda-HA511	Work Complete	OTHER	HA511 door	07/19/2013	09/10/2013	09/19/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
169	nevin-NE408	Work Complete	OTHER	NE408 vacancy	07/19/2013	09/16/2013	09/30/2013	v0003054 - SHOWTIME CONSTRUCTION IN	874.11
173	hacienda-HA109	Work Complete	PLUMBING	HA109 stoppage	07/22/2013	08/25/2013	09/04/2013	v0002938 - PREFERRED PLUMBING & DRA	0

174	friend-FM251	Work Complete	ELECTRICAL	574 Stege burners	07/22/2013	09/10/2013	09/17/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
176	nystrom-NV191	Work Complete	OTHER	233 16th gutter	07/22/2013	09/10/2013	09/11/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
178	nystrom-NV130	Work Complete	PLUMBING	1311 Maine toilet	07/22/2013	07/23/2013	07/26/2013	-	0
180	hacienda-HA404	Work Complete	PLUMBING	HA404 leak	07/22/2013	07/22/2013	07/22/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
188	nevin-NE412	Work Complete	PLUMBING	NE412 leak	07/23/2013	09/05/2013	09/17/2013	-	0
193	nevin-NE218	Work Complete	ELECTRICAL	NE218 outlets	07/23/2013	08/25/2013	09/02/2013	v0003246 - STRONGBUILT CONSTRUCTION	11.99
208	triangle-TC77	Work Complete	SERVICE	992 TC roaches	07/25/2013	07/26/2013	07/30/2013	v0003068 - OMEGA PEST CONTROL	0
209	triangle-TC84	Work Complete	OTHER	974 TC sdoor	07/25/2013	09/16/2013	09/18/2013	v0003246 - STRONGBUILT CONSTRUCTION	92.18
22	friend-FM248	Work Complete	SERVICE	FM Office lock repair	07/02/2013	07/08/2013	07/22/2013	v0002935 - B&B LOCKMSMITH	0
232	triangle-TC36	Work Complete	SERVICE	915 TC sdoor	07/26/2013	09/10/2013	09/12/2013	v0003246 - STRONGBUILT CONSTRUCTION	84.99
234	triangle-TC32	Work Complete	PLUMBING	935 9th Shower	07/26/2013	09/10/2013	09/13/2013	v0003246 - STRONGBUILT CONSTRUCTION	19.53
239	hacienda-HA414	Work Complete	OTHER	HA414 Front door	07/29/2013	09/10/2013	09/18/2013	v0003246 - STRONGBUILT CONSTRUCTION	7.34
25	hacienda-HA105	Work Complete	OTHER	HA105 doors	07/02/2013	07/09/2013	07/10/2013	v0003283 - OAKLAND CONSTRUCTION GR	351.79
250	friend-FM249	Work Complete	SERVICE	570 Stege key	07/30/2013	08/05/2013	08/26/2013	-	0
253	friend-FM238	Work Complete	OTHER	546 Stege c02 battery	07/31/2013	08/05/2013	08/08/2013	-	6.04
258	nevin-NE602	Work Complete	OTHER	NE602 refrig.	08/05/2013	08/06/2013	08/06/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
26	hacienda-HA109	Work Complete	SERVICE	HA109 smoke	07/02/2013	07/09/2013	07/14/2013	v0003283 - OAKLAND CONSTRUCTION GR	11.49
260	hacienda-HA316	Work Complete	SERVICE	HA316 roaches	08/06/2013	08/13/2013	09/05/2013	v0003068 - OMEGA PEST CONTROL	0
264	nystrom-NV127	Work Complete	SERVICE	250 S13 mice	08/06/2013	08/25/2013	08/29/2013	v0003068 - OMEGA PEST CONTROL	0
265	hacienda-HA414	Work Complete	SERVICE	HA414 Stove	08/06/2013	08/07/2013	08/07/2013	-	0
267	hacienda-HA202	Work Complete	OTHER	HA202 window	08/06/2013	08/12/2013	08/12/2013	-	13.99
269	nystrom-NV110	Work Complete	SERVICE	351 MWS keys	08/06/2013	08/07/2013	08/08/2013	v0002935 - B&B LOCKMSMITH	0
27	hacienda-HA111	Work Complete	SERVICE	HA111 misc.	07/02/2013	07/09/2013	07/11/2013	v0003283 - OAKLAND CONSTRUCTION GR	2.03
272	hacienda-HA414	Work Complete	SERVICE	HA414 mice	08/07/2013	08/12/2013	08/13/2013	v0003068 - OMEGA PEST CONTROL	0
274	nevin-NE102	Work Complete	SERVICE	NE102 no heat	08/07/2013	10/05/2013	10/17/2013	v0003237 - ALPHA DESIGN PLANNING/CO	140.8
278	hacienda-HA112	Work Complete	SERVICE	HA112 roaches	08/08/2013	08/13/2013	08/20/2013	v0003068 - OMEGA PEST CONTROL	0
279	hacienda-HA407	Work Complete	SERVICE	HA407 roaches	08/08/2013	08/13/2013	08/13/2013	v0003068 - OMEGA PEST CONTROL	0
28	hacienda-HA112	Work Complete	ELECTRICAL	HA112 elec	07/02/2013	07/09/2013	07/14/2013	v0003283 - OAKLAND CONSTRUCTION GR	11.99
283	hacienda-	Work Complete	SERVICE	HAOffice roaches	08/08/2013	08/13/2013	08/13/2013	v0003068 - OMEGA PEST CONTROL	0
284	hacienda-HA204	Work Complete	SERVICE	HA204 roaches	08/08/2013	08/13/2013	08/13/2013	v0003068 - OMEGA PEST CONTROL	0
285	hacienda-HA104	Work Complete	SERVICE	HA104 roaches	08/08/2013	08/13/2013	08/13/2013	v0003068 - OMEGA PEST CONTROL	0
286	triangle-TC51	Work Complete	SERVICE	948 9th trees	08/08/2013	08/20/2013	10/07/2013	v0003246 - STRONGBUILT CONSTRUCTION	0

287	nevin-NE520	Work Complete	OTHER	NE520 cabinet	08/09/2013	10/05/2013	10/16/2013	v0003237 - ALPHA DESIGN PLANNING/CO	0
29	hacienda-HA113	Work Complete		HA113	07/02/2013	07/09/2013	07/10/2013	v0003283 - OAKLAND CONSTRUCTION GR	12.83
30	hacienda-HA115	Work Complete	PLUMBING	HA115 leak	07/02/2013	07/09/2013	07/11/2013	v0003283 - OAKLAND CONSTRUCTION GR	7.8
303	hacienda-HA301	Work Complete	SERVICE	HA301 roaches	08/12/2013	08/25/2013	08/29/2013	v0003068 - OMEGA PEST CONTROL	0
304	triangle-TC24	Work Complete	PLUMBING	937 9th heater	08/12/2013	09/03/2013	09/03/2013	-	0
305	triangle-TC14	Work Complete	OTHER	913 Linc bins	08/12/2013	08/13/2013	08/19/2013	-	0
308	nystrom-NV159	Work Complete	SERVICE	1410 Florida lock	08/13/2013	08/25/2013	08/25/2013	v0002935 - B&B LOCKMSMITH	0
31	hacienda-HA116	Work Complete	ELECTRICAL	HA116 misc	07/02/2013	07/09/2013	07/11/2013	v0003283 - OAKLAND CONSTRUCTION GR	4.63
310	nystrom-NV170	Work Complete	ELECTRICAL	260 MWS leak	08/13/2013	08/25/2013	08/27/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
311	nevin-NE207	Work Complete	SERVICE	NE207 roaches	08/13/2013	08/19/2013	08/20/2013	v0003068 - OMEGA PEST CONTROL	0
312	hacienda-HA403	Work Complete	SERVICE	HA403 lock	08/13/2013	08/13/2013	08/13/2013	v0002935 - B&B LOCKMSMITH	0
32	hacienda-HA213	Work Complete	PLUMBING	HA213 sink	07/02/2013	07/09/2013	07/10/2013	v0003283 - OAKLAND CONSTRUCTION GR	2.91
328	hacienda-HA316	Work Complete	PLUMBING	HA316 Heater	08/14/2013	08/25/2013	09/17/2013	v0003246 - STRONGBUILT CONSTRUCTION	81.09
33	hacienda-HA218	Work Complete	ELECTRICAL	HA218 smoke	07/02/2013	07/09/2013	07/11/2013	v0003283 - OAKLAND CONSTRUCTION GR	11.49
333	friend-FM249	Work Complete	OTHER	570 Stege cabinet	08/14/2013	09/10/2013	09/11/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
335	hacienda-HA204	Work Complete	PLUMBING	HA204 stoppage	08/07/2013	08/07/2013	08/07/2013	v0002938 - PREFERRED PLUMBING & DRA	8.13
338	hacienda-HA113	Work Complete	SERVICE	HA113 roaches	08/15/2013	08/25/2013	08/29/2013	v0003068 - OMEGA PEST CONTROL	0
339	triangle-TC63	Work Complete	ELECTRICAL	955 8th switch	08/15/2013	09/10/2013	09/13/2013	v0003246 - STRONGBUILT CONSTRUCTION	1.05
34	triangle-TC96	Work Complete	PLUMBING	948TC plumbing	07/02/2013	07/09/2013	07/14/2013	v0003283 - OAKLAND CONSTRUCTION GR	66.28
340	nystrom-NV126	Work Complete	PLUMBING	322 13th No hot water	08/15/2013	08/16/2013	08/16/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
341	hacienda-HA102	Work Complete	SERVICE	HA102 roaches	08/16/2013	08/25/2013	08/29/2013	v0003068 - OMEGA PEST CONTROL	0
342	friend-FM242	Work Complete	ELECTRICAL	554 Stege oven	08/16/2013	08/31/2013	09/03/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
343	triangle-TC58	Work Complete	OTHER	978 8th seat	08/16/2013	08/16/2013	08/19/2013	-	0
344	hacienda-HA111	Work Complete	SERVICE	HA111 roaches	08/16/2013	08/25/2013	08/29/2013	v0003068 - OMEGA PEST CONTROL	0
346	triangle-TC61	Work Complete	ELECTRICAL	959 9th bulb	08/16/2013	09/10/2013	09/13/2013	v0003246 - STRONGBUILT CONSTRUCTION	1.1
35	nevin-NE504	Work Complete	PLUMBING	NE504 leak	07/02/2013	07/09/2013	07/14/2013	v0003283 - OAKLAND CONSTRUCTION GR	3.94
351	nystrom-NV169	Work Complete	PLUMBING	250 MWS heat	08/19/2013	08/25/2013	08/27/2013	v0003246 - STRONGBUILT CONSTRUCTION	32.1
352	nystrom-NV131	Work Complete	PLUMBING	1317 Maine heat	08/20/2013	08/23/2013	08/27/2013	v0003246 - STRONGBUILT CONSTRUCTION	26.96
354	friend-FM249	Work Complete	PLUMBING	570 Stege stoppage	08/20/2013	08/20/2013	08/20/2013	v0002938 - PREFERRED PLUMBING & DRA	0
356	nystrom-NV113	Work Complete	SERVICE	337 MWS locks	08/20/2013	08/25/2013	08/28/2013	v0002935 - B&B LOCKMSMITH	13.98
358	hacienda-HA110	Work Complete	SERVICE	HA110 roaches	08/21/2013	08/25/2013	08/29/2013	v0003068 - OMEGA PEST CONTROL	0
36	nystrom-NV137	Work Complete	ELECTRICAL	249 MWS light	07/02/2013	07/09/2013	08/30/2013	v0003283 - OAKLAND CONSTRUCTION GR	5.97

364	triangle-TC44	Work Complete	PLUMBING	947 9th faucet	08/21/2013	08/25/2013	09/10/2013	v0003246 - STRONGBUILT CONSTRUCTION	1.96
365	nevin-NE304	Work Complete	OTHER	NE304 crod	08/21/2013	10/05/2013	10/16/2013	v0003237 - ALPHA DESIGN PLANNING/CO	0
366	hacienda-HA513	Work Complete	ELECTRICAL	HA513 bulb	08/21/2013	09/03/2013	09/04/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
37	friend-	Work Complete	ELECTRICAL	FM keycard	07/02/2013	08/07/2013	08/08/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
370	nystrom-NV154	Work Complete	PLUMBING	219 15th leak	08/21/2013	08/21/2013	08/21/2013	v0002938 - PREFERRED PLUMBING & DRA	0
372	hacienda-HA207	Work Complete	SERVICE	HA207 locks	08/21/2013	08/21/2013	08/22/2013	-	0
374	triangle-TC31	Work Complete	OTHER	934 9th vacant	08/21/2013	09/13/2013	10/03/2013	v0003246 - STRONGBUILT CONSTRUCTION	892.94
378	hacienda-HA502	Work Complete	SERVICE	HA502 Bedbug	08/22/2013	08/25/2013	08/27/2013	v0003068 - OMEGA PEST CONTROL	0
38	nystrom-NV192	Work Complete		241 16th oven	07/02/2013	07/09/2013	07/11/2013	v0003283 - OAKLAND CONSTRUCTION GR	0
383	nystrom-NV166	Work Complete	PLUMBING	236 MWS handle	08/23/2013	08/23/2013	08/26/2013	v0003246 - STRONGBUILT CONSTRUCTION	1.79
386	friend-FM266	Work Complete	ELECTRICAL	604 Stege oven	08/23/2013	08/31/2013	09/03/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
388	nystrom-NV118	Work Complete	OTHER	315 MWS oven	08/15/2013	09/10/2013	09/18/2013	v0003246 - STRONGBUILT CONSTRUCTION	30.59
39	nevin-NE416	Work Complete	PLUMBING	NE416 leak	07/02/2013	07/09/2013	07/10/2013	v0003283 - OAKLAND CONSTRUCTION GR	0
392	nystrom-NV176	Work Complete	PLUMBING	263 S15th leak	08/26/2013	08/26/2013	08/26/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
393	triangle-TC5	Work Complete	PLUMBING	811 Linc leak	08/26/2013	08/26/2013	08/29/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
394	triangle-TC58	Work Complete	OTHER	978 8th tub str.	08/26/2013	09/10/2013	09/13/2013	v0003246 - STRONGBUILT CONSTRUCTION	0.41
395	nystrom-NV188	Work Complete	SERVICE	251 16th locks	08/26/2013	08/26/2013	08/27/2013	v0002935 - B&B LOCKSMITH	0
397	hacienda-HA209	Work Complete	SERVICE	HA209 roaches	08/26/2013	08/26/2013	08/29/2013	v0003068 - OMEGA PEST CONTROL	0
398	nystrom-NV136	Work Complete	PLUMBING	251 MWS main	08/26/2013	08/26/2013	08/26/2013	v0002938 - PREFERRED PLUMBING & DRA	0
399	triangle-TC47	Work Complete	ELECTRICAL	941 9th heat	08/26/2013	09/10/2013	09/19/2013	v0003246 - STRONGBUILT CONSTRUCTION	76.43
40	nystrom-NV198	Work Complete	PLUMBING	1514 Fl. oven	07/02/2013	07/09/2013	07/11/2013	v0003283 - OAKLAND CONSTRUCTION GR	29.54
401	nystrom-NV140	Work Complete	PLUMBING	237 MWS toilet	08/27/2013	08/29/2013	09/01/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
405	hacienda-HA510	Work Complete	SERVICE	HA510 roaches	08/28/2013	08/28/2013	09/03/2013	v0003068 - OMEGA PEST CONTROL	0
406	hacienda-HA510	Work Complete	OTHER	HA510 Mold/caulking/linole	08/28/2013	08/28/2013	09/09/2013	v0003246 - STRONGBUILT CONSTRUCTION	13.92
407	hacienda-HA510	Work Complete	PLUMBING	HA510 leaks	08/28/2013	08/28/2013	09/10/2013	v0003246 - STRONGBUILT CONSTRUCTION	10.17
408	hacienda-HA301	Work Complete	OTHER	HA301 Graffiti	08/28/2013	09/10/2013	09/17/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
409	hacienda-HA204	Work Complete	PLUMBING	HA204 flushing	08/28/2013	08/28/2013	08/28/2013	v0003246 - STRONGBUILT CONSTRUCTION	1.65
41	hacienda-HA412	Work Complete	OTHER	HA412 crack	07/02/2013	07/09/2013	07/11/2013	v0003283 - OAKLAND CONSTRUCTION GR	0
410	nystrom-NV149	Work Complete	OTHER	1310 FL toilet leak	08/28/2013	08/28/2013	08/30/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
411	nystrom-NV149	Work Complete	OTHER	1310 FL bulb	08/28/2013	09/10/2013	09/11/2013	v0003246 - STRONGBUILT CONSTRUCTION	6.36
412	friend-FM237	Work Complete	OTHER	544 S patio	08/28/2013	09/10/2013	09/19/2013	v0003246 - STRONGBUILT CONSTRUCTION	28.35
413	hacienda-HA513	Work Complete	ELECTRICAL	HA513 bulb	08/28/2013	09/03/2013	09/03/2013	-	0

415	nevin-NE417	Work Complete	SERVICE	NE417 roaches	08/29/2013	08/29/2013	09/03/2013	v0003068 - OMEGA PEST CONTROL	0
416	hacienda-HA211	Work Complete	OTHER	HA211 door	08/29/2013	09/10/2013	09/19/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
417	hacienda-HA222	Work Complete	ELECTRICAL	HA222 oven	08/29/2013	08/29/2013	08/29/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
418	friend-FM242	Work Complete	ELECTRICAL	554 Stege heat	08/29/2013	08/31/2013	09/03/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
420	hacienda-HA301	Work Complete	PLUMBING	HA301 heat	08/30/2013	09/10/2013	09/17/2013	v0003246 - STRONGBUILT CONSTRUCTION	81.09
422	nevin-NE217	Work Complete	PLUMBING	NE217 faucet	08/30/2013	09/03/2013	09/03/2013	-	55.04
423	triangle-TC83	Work Complete	SERVICE	976 TC glass	08/30/2013	09/03/2013	09/05/2013	-	0
424	hacienda-HA221	Work Complete	OTHER	HA221 ceiling	08/30/2013	09/03/2013	09/03/2013	-	0
425	nystrom-NV110	Work Complete	OTHER	351 MWS mntc	08/30/2013	09/10/2013	09/13/2013	v0003246 - STRONGBUILT CONSTRUCTION	22.97
426	nystrom-NV134	Work Complete	OTHER	263 MWS locks	08/30/2013	08/30/2013	08/30/2013	v0003459 - SOMERS LOCK SHOP	0
428	nevin-NE314	Work Complete	PLUMBING	NE314 toilet crk	09/03/2013	09/03/2013	09/04/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
429	triangle-TC25	Work Complete	PLUMBING	935 9 oven	09/03/2013	10/01/2013	10/02/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
430	hacienda-HA506	Work Complete	SERVICE	HA506 roaches	09/03/2013	09/03/2013	09/10/2013	v0003068 - OMEGA PEST CONTROL	0
431	nevin-NE509	Work Complete	SERVICE	NE509 roaches	09/03/2013	09/03/2013	09/10/2013	v0003068 - OMEGA PEST CONTROL	0
432	triangle-TC42	Work Complete	PLUMBING	966 9th leak	09/02/2013	09/02/2013	09/19/2013	v0002938 - PREFERRED PLUMBING & DRA	2.66
433	hacienda-HA221	Work Complete		HA221 ceiling	09/03/2013	09/03/2013	09/05/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
434	hacienda-HA321	Work Complete	OTHER	HA326 tile	09/03/2013	09/03/2013	09/04/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
435	nevin-NE709	Work Complete	OTHER	NE709 vacant	09/03/2013	09/16/2013	09/26/2013	v0003250 - MICHAEL'S FLR COV/MJ8 GEN	726.88
437	nystrom-NV104	Work Complete	PLUMBING	1311 Virgina plumbing	08/27/2013	08/27/2013	08/27/2013	v0002938 - PREFERRED PLUMBING & DRA	0
438	hacienda-HA306	Work Complete	SERVICE	HA306 roaches	09/03/2013	09/10/2013	09/10/2013	v0003068 - OMEGA PEST CONTROL	0
439	nevin-NE521	Work Complete		NE521 brk wndw	09/03/2013	09/03/2013	09/06/2013	v0002937 - ALL GLASS	0
440	nevin-NE709	Work Complete		NE709 brk wndw	09/03/2013	09/03/2013	09/05/2013	v0002937 - ALL GLASS	0
441	hacienda-	Work Complete	ELECTRICAL	HAC lights	09/04/2013	09/04/2013	09/04/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
442	hacienda-HA401	Work Complete	OTHER	HA401 door	09/04/2013	09/16/2013	09/17/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
443	friend-FM231	Work Complete	OTHER	617 S37 tile	09/04/2013	09/10/2013	09/19/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
445	nevin-	Work Complete	SERVICE	Admin roaches	09/04/2013	09/10/2013	09/10/2013	v0003068 - OMEGA PEST CONTROL	0
447	nevin-NE307	Work Complete	PLUMBING	NE307 leak	09/04/2013	09/16/2013	09/19/2013	v0003246 - STRONGBUILT CONSTRUCTION	10.32
449	friend-FM243	Work Complete	OTHER	556 Stege sdoor	08/13/2013	09/04/2013	09/04/2013	v0003246 - STRONGBUILT CONSTRUCTION	84.99
45	nystrom-NV165	Work Complete	SERVICE	235 MWS crod	07/02/2013	07/09/2013	09/10/2013	v0003283 - OAKLAND CONSTRUCTION GR	0
450	nystrom-NV184	Work Complete	PLUMBING	1517 Maine water/gas	09/06/2013	09/06/2013	09/11/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
451	hacienda-HA221	Work Complete	PLUMBING	HA221 heat	09/06/2013	09/16/2013	09/18/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
452	hacienda-HA202	Work Complete	OTHER	HA202 blinds	09/06/2013	10/05/2013	10/15/2013	v0003237 - ALPHA DESIGN PLANNING/CO	29.59

455	hacienda-HA111	Work Complete	SERVICE	HA111 roaches	09/06/2013	09/10/2013	09/10/2013	v0003068 - OMEGA PEST CONTROL	0
458	nystrom-NV131	Work Complete		1317 Maine elect.	09/06/2013	09/10/2013	09/10/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
46	triangle-TC81	Work Complete	PLUMBING	980 TC faucet	07/02/2013	07/09/2013	07/14/2013	v0003283 - OAKLAND CONSTRUCTION GR	63.42
460	hacienda-HA107	Work Complete	PLUMBING	HA107 stoppage	09/16/2013	09/16/2013	09/16/2013	v0002938 - PREFERRED PLUMBING & DRA	0
463	friend-FM225	Work Complete	ELECTRICAL	605 S37 heater	09/10/2013	09/12/2013	09/13/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
464	friend-FM240	Work Complete	OTHER	550 Stege blinds	09/10/2013	10/05/2013	10/17/2013	v0003237 - ALPHA DESIGN PLANNING/CO	0
47	triangle-TC19	Work Complete	OTHER	926 8th door	07/02/2013	07/09/2013	07/14/2013	v0003283 - OAKLAND CONSTRUCTION GR	10.64
472	nevin-NE215	Work Complete	PLUMBING	NE215 leak	09/10/2013	10/05/2013	10/16/2013	v0003237 - ALPHA DESIGN PLANNING/CO	0
473	nevin-NE225	Work Complete	OTHER	NE225 cdoor	09/10/2013	10/05/2013	10/16/2013	v0003237 - ALPHA DESIGN PLANNING/CO	0
476	hacienda-HA209	Work Complete	SERVICE	HA209 roaches	09/10/2013	09/17/2013	09/17/2013	v0003068 - OMEGA PEST CONTROL	0
477	nevin-NE202	Work Complete	OTHER	NE202 hinges	09/11/2013	10/05/2013	10/16/2013	v0003237 - ALPHA DESIGN PLANNING/CO	0
48	nystrom-NV101	Work Complete	ELECTRICAL	350 S13th heater	07/02/2013	07/09/2013	07/11/2013	v0003283 - OAKLAND CONSTRUCTION GR	0
481	nystrom-NV102	Work Complete	OTHER	256 S13 cdoors	09/13/2013	10/05/2013	10/13/2013	v0003237 - ALPHA DESIGN PLANNING/CO	0
482	nystrom-	Work Complete	OTHER	Nystrom trash	09/13/2013	09/16/2013	09/17/2013	-	0
485	nystrom-NV168	Work Complete	OTHER	248 MWS vandalism	09/16/2013	09/16/2013	09/16/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
486	friend-FM263	Work Complete	PLUMBING	598 Stege handle	09/16/2013	09/16/2013	09/17/2013	-	11.94
489	nystrom-NV182	Work Complete	PLUMBING	264 15th tub	09/16/2013	09/16/2013	09/19/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
49	triangle-TC15	Work Complete	OTHER	915 Linc window	07/02/2013	07/09/2013	07/14/2013	v0003283 - OAKLAND CONSTRUCTION GR	0
492	friend-FM215	Work Complete	ELECTRICAL	561 S37th fan	09/13/2013	09/26/2013	10/04/2013	v0003246 - STRONGBUILT CONSTRUCTION	41.98
497	hacienda-HA204	Work Complete	SERVICE	HA204 roaches	09/16/2013	09/17/2013	09/17/2013	v0003068 - OMEGA PEST CONTROL	0
498	triangle-TC39	Work Complete	PLUMBING	944 8th stove	09/16/2013	09/30/2013	10/04/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
499	nevin-	Work Complete	OTHER	Nevin CC	09/16/2013	10/05/2013	10/16/2013	v0003237 - ALPHA DESIGN PLANNING/CO	0
50	hacienda-HA502	Work Complete	SERVICE	HA502 mice	07/02/2013	07/09/2013	07/11/2013	v0003283 - OAKLAND CONSTRUCTION GR	3.65
500	nystrom-NV167	Work Complete	SERVICE	242 MWS ants	09/13/2013	09/16/2013	09/17/2013	v0003068 - OMEGA PEST CONTROL	0
501	nevin-NE507	Work Complete	PLUMBING	NE507 toilet	09/11/2013	10/05/2013	10/16/2013	v0003237 - ALPHA DESIGN PLANNING/CO	0
502	nevin-NE614	Work Complete	PLUMBING	NE614 shower	09/17/2013	09/17/2013	11/09/2013	v0002938 - PREFERRED PLUMBING & DRA	0
51	hacienda-HA217	Work Complete	OTHER	HA217 window	07/02/2013	07/09/2013	07/10/2013	v0003283 - OAKLAND CONSTRUCTION GR	6.48
510	hacienda-HA101	Work Complete		HA101 refrig.	09/12/2013	09/16/2013	09/20/2013	-	0
513	nevin-NE412	Work Complete	PLUMBING	NE412 stoppage	09/04/2013	09/04/2013	09/04/2013	v0002938 - PREFERRED PLUMBING & DRA	0
515	friend-	Work Complete	OTHER	FM janitorial	09/18/2013	09/19/2013	09/19/2013	-	265.56
516	hacienda-	Work Complete	OTHER	HA Graffiti	09/16/2013	09/17/2013	09/18/2013	-	0
517	hacienda-HA511	Work Complete	OTHER	HA 511 stove	09/19/2013	09/26/2013	10/17/2013	v0003237 - ALPHA DESIGN PLANNING/CO	0

518	nevin-NE307	Work Complete	PLUMBING	NE307 leak	09/19/2013	09/29/2013	10/02/2013	v0003246 - STRONGBUILT CONSTRUCTION	5.27
519	hacienda-HA414	Work Complete		HA414 wall	09/19/2013	09/25/2013	09/27/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
52	hacienda-	Work Complete	OTHER	HAC Grafitti	07/02/2013	07/09/2013	07/11/2013	v0003283 - OAKLAND CONSTRUCTION GR	0
520	hacienda-	Work Complete		HA security office	09/19/2013	09/26/2013	09/26/2013	v0003246 - STRONGBUILT CONSTRUCTION	15.6
521	hacienda-HA101	Work Complete		HA101 refrig out	09/19/2013	09/19/2013	09/19/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
525	hacienda-HA317	Work Complete	PLUMBING	HA317 sink	09/23/2013	09/23/2013	09/24/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
526	nystrom-NV182	Work Complete	PLUMBING	264 15 tub/toilet	09/23/2013	09/24/2013	09/24/2013	v0003246 - STRONGBUILT CONSTRUCTION	9.83
528	nevin-NE218	Work Complete	SERVICE	NE218 roaches	09/23/2013	09/24/2013	10/15/2013	v0003068 - OMEGA PEST CONTROL	0
53	nystrom-NV105	Work Complete	OTHER	1317 Virginia elec	07/03/2013	07/09/2013	07/15/2013	v0003283 - OAKLAND CONSTRUCTION GR	20.66
531	friend-FM261	Work Complete	OTHER	594 Stege bushes	09/23/2013	09/25/2013	10/01/2013	-	0
536	hacienda-HA105	Work Complete	SERVICE	HA105 mildew	09/24/2013	10/05/2013	10/15/2013	v0003237 - ALPHA DESIGN PLANNING/CO	0
537	nystrom-NV139	Work Complete	OTHER	239 MWS heat	09/20/2013	09/30/2013	10/02/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
538	nystrom-NV107	Work Complete	OTHER	1329 Virginia door	09/25/2013	09/25/2013	09/26/2013	v0003246 - STRONGBUILT CONSTRUCTION	19.64
539	nystrom-NV168	Work Complete	ELECTRICAL	248 MWS elec.	09/25/2013	09/30/2013	10/23/2013	v0003246 - STRONGBUILT CONSTRUCTION	15.95
540	nevin-	Work Complete	OTHER	NE bench	09/25/2013	09/27/2013	09/28/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
541	friend-FM267	Work Complete	SERVICE	606 Stege locks	09/24/2013	09/24/2013	09/24/2013	v0002935 - B&B LOCKMSMITH	0
542	hacienda-HA405	Work Complete	SERVICE	HA405 eviction	09/24/2013	09/25/2013	09/25/2013	v0002935 - B&B LOCKMSMITH	6.99
543	friend-	Work Complete	ELECTRICAL	FM timer	09/23/2013	09/24/2013	10/24/2013	-	0
544	hacienda-HA421	Work Complete	OTHER	HA421 leak	09/26/2013	09/26/2013	09/27/2013	v0003246 - STRONGBUILT CONSTRUCTION	35.06
545	friend-	Work Complete	ELECTRICAL	FM Timer breaker	09/27/2013	09/27/2013	09/30/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
546	friend-FM250	Work Complete	PLUMBING	572 Stege h20	09/27/2013	09/27/2013	09/27/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
547	nevin-NE206	Work Complete	SERVICE	NE206 roaches	09/27/2013	10/05/2013	10/15/2013	v0003068 - OMEGA PEST CONTROL	0
548	nystrom-NV172	Work Complete	OTHER	1407 Maine hinge	09/27/2013	10/05/2013	10/16/2013	v0003237 - ALPHA DESIGN PLANNING/CO	5.97
549	nystrom-NV172	Work Complete	PLUMBING	1407 Maine stoppage	09/26/2013	09/26/2013	09/26/2013	v0002938 - PREFERRED PLUMBING & DRA	0
550	nystrom-NV154	Work Complete	PLUMBING	219 S15 toilet	09/27/2013	10/05/2013	10/15/2013	v0003237 - ALPHA DESIGN PLANNING/CO	57.3
557	nystrom-NV157	Work Complete		1420 Florida main	09/30/2013	09/30/2013	09/30/2013	v0002938 - PREFERRED PLUMBING & DRA	0
559	friend-FM225	Work Complete	PLUMBING	605 S37th leak	09/17/2013	09/17/2013	09/17/2013	-	44.78
56	hacienda-HA223	Work Complete	PLUMBING	HA223 leak	07/03/2013	07/08/2013	07/26/2013	v0002938 - PREFERRED PLUMBING & DRA	0
560	nystrom-NV167	Work Complete	PLUMBING	242 MWS main	09/30/2013	09/30/2013	09/30/2013	v0002938 - PREFERRED PLUMBING & DRA	5.32
561	friend-FM250	Work Complete	OTHER	572 Stege carpet	09/30/2013	09/30/2013	10/01/2013	v0002996 - USA CARPET	0
563	hacienda-HA511	Work Complete	PLUMBING	HA511 stoppage	09/30/2013	09/30/2013	09/30/2013	-	0
564	triangle-TC89	Work Complete	SERVICE	964TC roaches	09/30/2013	10/05/2013	10/08/2013	v0003068 - OMEGA PEST CONTROL	0

565	triangle-TC89	Work Complete	PLUMBING	964TC door/toilet	09/30/2013	09/30/2013	09/30/2013	v0003246 - STRONGBUILT CONSTRUCTION	4.51
566	triangle-TC90	Work Complete	SERVICE	962 TC roaches	09/30/2013	10/05/2013	10/08/2013	v0003068 - OMEGA PEST CONTROL	0
567	nevin-NE104	Work Complete	SERVICE	NE104 roaches	09/30/2013	10/05/2013	10/15/2013	v0003068 - OMEGA PEST CONTROL	0
568	nevin-NE102	Work Complete	SERVICE	NE102 roaches	09/30/2013	10/05/2013	10/15/2013	v0003068 - OMEGA PEST CONTROL	0
569	nevin-NE412	Work Complete	ELECTRICAL	NE421 bulbs	09/30/2013	10/01/2013	10/01/2013	-	6.78
57	friend-FM222	Work Complete	SERVICE	579 S37 lock in	07/03/2013	07/03/2013	07/03/2013	-	0
570	friend-FM252	Work Complete	OTHER	576 Stege batt	09/30/2013	10/01/2013	10/01/2013	v0003246 - STRONGBUILT CONSTRUCTION	1.25
571	nystrom-NV112	Work Complete	PLUMBING	341MWS cold	09/27/2013	09/30/2013	09/30/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
572	triangle-TC77	Work Complete	PLUMBING	992TC h20	09/30/2013	09/30/2013	10/03/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
573	friend-FM224	Work Complete	OTHER	603 S37 refrig.	09/30/2013	09/30/2013	10/01/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
574	hacienda-HA420	Work Complete	PLUMBING	HA420 leak	10/01/2013	10/02/2013	10/03/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
575	friend-FM235	Work Complete	PLUMBING	540 Stege drains	10/01/2013	10/01/2013	10/01/2013	v0002938 - PREFERRED PLUMBING & DRA	0
576	friend-FM237	Work Complete	PLUMBING	544 Stege drains	10/01/2013	10/01/2013	10/10/2013	v0002938 - PREFERRED PLUMBING & DRA	0
577	nevin-NE207	Work Complete	SERVICE	NE207 roaches	10/01/2013	10/05/2013	10/15/2013	v0003068 - OMEGA PEST CONTROL	0
578	triangle-TC58	Work Complete	PLUMBING	978 8th stoppage	10/02/2013	10/02/2013	10/02/2013	v0002938 - PREFERRED PLUMBING & DRA	2.66
579	triangle-TC92	Work Complete	PLUMBING	956 TC pantry	10/02/2013	10/02/2013	10/02/2013	v0002938 - PREFERRED PLUMBING & DRA	0
582	hacienda-HA104	Work Complete	PLUMBING	HA104 drains	10/03/2013	10/03/2013	10/03/2013	v0002938 - PREFERRED PLUMBING & DRA	0
583	hacienda-HA104	Work Complete	SERVICE	HA104 roaches	10/03/2013	10/05/2013	10/08/2013	v0003068 - OMEGA PEST CONTROL	0
584	triangle-TC47	Work Complete	PLUMBING	941 9 stoppage	10/03/2013	10/03/2013	10/03/2013	v0002938 - PREFERRED PLUMBING & DRA	0
585	friend-FM264	Work Complete	OTHER	600 Stege cdor	10/03/2013	10/05/2013	10/17/2013	v0003237 - ALPHA DESIGN PLANNING/CO	0
587	nystrom-NV105	Work Complete	SERVICE	1317 Virginia roaches	10/03/2013	10/05/2013	10/17/2013	v0003068 - OMEGA PEST CONTROL	0
588	nystrom-NV127	Work Complete	SERVICE	250 MWS mice	10/03/2013	10/05/2013	10/17/2013	v0003068 - OMEGA PEST CONTROL	0
589	nevin-NE205	Work Complete	PLUMBING	NE205 toilet	10/01/2013	10/01/2013	10/02/2013	v0002938 - PREFERRED PLUMBING & DRA	22.71
590	hacienda-HA304	Work Complete	SERVICE	HA304 roaches	10/03/2013	10/05/2013	10/08/2013	v0003068 - OMEGA PEST CONTROL	0
591	hacienda-HA507	Work Complete	SERVICE	HA507 roaches	10/03/2013	10/05/2013	10/15/2013	v0003068 - OMEGA PEST CONTROL	0
592	friend-FM232	Work Complete	SERVICE	619 S37 glass	10/04/2013	10/04/2013	10/04/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
593	hacienda-HA406	Work Complete	SERVICE	HA406 mice/roach	10/04/2013	10/05/2013	10/08/2013	v0003068 - OMEGA PEST CONTROL	0
594	hacienda-HA407	Work Complete	SERVICE	HA407 mice/roach	10/04/2013	10/05/2013	10/08/2013	v0003068 - OMEGA PEST CONTROL	0
595	nystrom-NV134	Work Complete	OTHER	263 MWS break in	10/04/2013	10/04/2013	10/04/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
596	nystrom-NV147	Work Complete	OTHER	1320 Florida locks	10/03/2013	10/03/2013	10/07/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
597	friend-FM224	Work Complete	OTHER	603 S37 window	10/04/2013	10/05/2013	10/17/2013	v0003237 - ALPHA DESIGN PLANNING/CO	0
598	nystrom-NV184	Work Complete	PLUMBING	1517 Maine head	10/04/2013	10/04/2013	10/08/2013	v0003246 - STRONGBUILT CONSTRUCTION	17.46



599	friend-FM247	Work Complete	OTHER	566 Stege heat	10/04/2013	10/04/2013	10/23/2013	v0003246 - STRONGBUILT CONSTRUCTION	26.96
600	nystrom-NV110	Work Complete	PLUMBING	351 MWS stoppage	10/04/2013	10/04/2013	10/04/2013	v0002938 - PREFERRED PLUMBING & DRA	0
601	nystrom-NV110	Work Complete	OTHER	351 MWS misc.	10/04/2013	10/04/2013	10/07/2013	v0003246 - STRONGBUILT CONSTRUCTION	11.49
602	nevin-NE725	Work Complete	SERVICE	NE725 carpet	09/25/2013	09/25/2013	09/26/2013	v0002996 - USA CARPET	0
603	nevin-	Work Complete	SERVICE	NE205 carpet	09/27/2013	09/27/2013	09/30/2013	v0002996 - USA CARPET	0
604	nevin-NE408	Work Complete	SERVICE	NE408 carpet	09/27/2013	09/27/2013	09/28/2013	v0002996 - USA CARPET	0
605	friend-FM239	Work Complete	OTHER	546 Stege door	10/04/2013	10/04/2013	10/04/2013	v0003246 - STRONGBUILT CONSTRUCTION	26.96
606	nevin-	Work Complete	OTHER	NE elevator	10/05/2013	10/05/2013	10/05/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
607	hacienda-	Work Complete	OTHER	HA windows	10/05/2013	10/05/2013	10/07/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
608	hacienda-HA309	Work Complete	PLUMBING	HA309 leak	10/03/2013	10/03/2013	10/03/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
609	hacienda-HA526	Work Complete	ELECTRICAL	HA526 lamp	10/07/2013	10/07/2013	11/08/2013	-	3.21
610	hacienda-HA306	Work Complete	ELECTRICAL	HA306 elec short	10/07/2013	10/07/2013	10/07/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
611	nystrom-NV168	Work Complete	SERVICE	248 MWS ants	10/07/2013	10/07/2013	10/17/2013	v0003068 - OMEGA PEST CONTROL	0
612	hacienda-HA317	Work Complete	OTHER	HA317 keys	10/04/2013	10/04/2013	10/04/2013	-	0
613	hacienda-HA109	Work Complete	SERVICE	HA108 cdor	10/07/2013	10/11/2013	10/15/2013	v0003237 - ALPHA DESIGN PLANNING/CO	0
614	hacienda-HA516	Work Complete	SERVICE	HA516 roaches	10/07/2013	10/07/2013	10/08/2013	v0003068 - OMEGA PEST CONTROL	0
617	triangle-TC52	Work Complete	PLUMBING	929TC leak	10/08/2013	10/09/2013	10/09/2013	v0002938 - PREFERRED PLUMBING & DRA	0
618	hacienda-HA414	Work Complete	OTHER	HA414 doors	10/08/2013	10/09/2013	10/10/2013	-	15.6
619	nystrom-NV168	Work Complete	OTHER	248MWS Blinds	10/08/2013	10/10/2013	10/10/2013	-	0
62	triangle-TC1	Work Complete	PLUMBING	801 Linc stoppage	07/03/2013	07/03/2013	07/03/2013	v0002938 - PREFERRED PLUMBING & DRA	0
620	triangle-TC30	Work Complete	PLUMBING	932 9th No hot water	10/08/2013	10/08/2013	10/10/2013	-	0
621	hacienda-HA201	Work Complete	SERVICE	HA201 roaches	10/08/2013	10/15/2013	10/15/2013	v0003068 - OMEGA PEST CONTROL	0
622	nystrom-NV183	Work Complete	OTHER	1515 Maine Racoons	10/08/2013	10/08/2013	10/08/2013	-	0
623	hacienda-HA219	Work Complete	OTHER	HA219 rack	10/08/2013	10/08/2013	10/09/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
624	friend-FM265	Work Complete	PLUMBING	602 Stege leak	10/08/2013	10/09/2013	10/10/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
625	triangle-TC88	Work Complete	PLUMBING	966TC stoppage	10/08/2013	10/09/2013	10/11/2013	v0002938 - PREFERRED PLUMBING & DRA	0
626	nevin-NE307	Work Complete	PLUMBING	NE307 Noise	10/08/2013	10/14/2013	10/15/2013	-	0
628	hacienda-HA204	Work Complete	PLUMBING	HA204 leak	10/08/2013	10/08/2013	10/09/2013	v0003246 - STRONGBUILT CONSTRUCTION	63.42
63	nystrom-NV194	Work Complete	PLUMBING	217 S 16th toilet	07/03/2013	07/03/2013	07/03/2013	v0002938 - PREFERRED PLUMBING & DRA	5.27
630	hacienda-HA402	Work Complete	OTHER	HA402 blinds	10/09/2013	10/16/2013	10/17/2013	-	15.6
633	nevin-NE214	Work Complete	PLUMBING	NE214 stoppage	10/09/2013	10/09/2013	10/09/2013	v0002938 - PREFERRED PLUMBING & DRA	0
635	hacienda-HA502	Work Complete	OTHER	HA502 mice	10/09/2013	10/15/2013	10/16/2013	v0003068 - OMEGA PEST CONTROL	0

636	hacienda-HA502	Work Complete	PLUMBING	HA502 heater	10/09/2013	10/10/2013	10/11/2013	-	81.09
638	nevin-NE104	Work Complete	SERVICE	NE104 roaches	10/09/2013	10/15/2013	10/15/2013	v0003068 - OMEGA PEST CONTROL	0
639	nevin-NE614	Work Complete	PLUMBING	NE614 faucet	10/09/2013	10/09/2013	10/09/2013	v0002938 - PREFERRED PLUMBING & DRA	0
640	hacienda-HA414	Work Complete	OTHER	HA414 misc	10/09/2013	10/10/2013	10/10/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
641	hacienda-HA414	Work Complete	SERVICE	HA414 roaches/mice	10/09/2013	10/15/2013	10/17/2013	v0003068 - OMEGA PEST CONTROL	0
646	triangle-TC96	Work Complete	PLUMBING	948 TC stoppage	10/15/2013	10/15/2013	10/15/2013	v0002938 - PREFERRED PLUMBING & DRA	0
648	hacienda-HA118	Work Complete	OTHER	HA118 burners	10/15/2013	10/16/2013	10/17/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
649	nystrom-NV114	Work Complete	PLUMBING	335MWS pipes	10/15/2013	10/15/2013	10/15/2013	v0002938 - PREFERRED PLUMBING & DRA	0
65	nystrom-NV107	Work Complete	PLUMBING	1329 V leak	07/05/2013	07/05/2013	07/05/2013	-	0
650	triangle-TC53	Work Complete	PLUMBING	937 TC stoppage	10/15/2013	10/15/2013	10/16/2013	v0002938 - PREFERRED PLUMBING & DRA	0
652	hacienda-HA109	Work Complete	PLUMBING	HA109 stoppage	10/15/2013	10/15/2013	10/16/2013	v0002938 - PREFERRED PLUMBING & DRA	0
653	hacienda-HA503	Work Complete	PLUMBING	HA503 loose toilet	10/09/2013	10/09/2013	10/10/2013	v0003246 - STRONGBUILT CONSTRUCTION	2.91
654	hacienda-HA207	Work Complete		HA207 faucet	10/09/2013	10/10/2013	10/10/2013	v0003246 - STRONGBUILT CONSTRUCTION	63.42
655	hacienda-HA102	Work Complete	PLUMBING	HA102 stoppage	10/11/2013	10/11/2013	10/11/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
657	hacienda-HA605	Work Complete	SERVICE	HA605 roaches	10/15/2013	10/22/2013	10/29/2013	v0003068 - OMEGA PEST CONTROL	0
660	nystrom-NV195	Work Complete	PLUMBING	207 S16th Toilet	10/16/2013	10/21/2013	11/05/2013	v0003246 - STRONGBUILT CONSTRUCTION	19.97
662	friend-FM250	Work Complete		572 Stege leak	10/16/2013	10/18/2013	10/18/2013	v0002938 - PREFERRED PLUMBING & DRA	0
663	friend-FM264	Work Complete	SERVICE	600 Stege mice	10/16/2013	10/16/2013	10/17/2013	v0003068 - OMEGA PEST CONTROL	0
665	friend-FM247	Work Complete	PLUMBING	566 Stege tub	10/04/2013	10/04/2013	10/04/2013	v0002938 - PREFERRED PLUMBING & DRA	0
666	hacienda-HA514	Work Complete	PLUMBING	HA514 leak/lamp	10/17/2013	10/21/2013	10/21/2013	v0003246 - STRONGBUILT CONSTRUCTION	8.6
667	nevin-NE206	Work Complete	SERVICE	NE206 roaches	10/14/2013	10/15/2013	10/15/2013	v0003068 - OMEGA PEST CONTROL	0
668	hacienda-HA419	Work Complete	OTHER	HA419 door	10/17/2013	10/17/2013	10/17/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
669	triangle-TC43	Work Complete	PLUMBING	949 9th stoppage	10/17/2013	10/18/2013	10/21/2013	v0002938 - PREFERRED PLUMBING & DRA	0
670	hacienda-HA107	Work Complete	ELECTRICAL	HA107 bulb	10/17/2013	10/17/2013	10/18/2013	-	3.52
671	hacienda-HA105	Work Complete	OTHER	HA105 door	10/17/2013	10/17/2013	10/17/2013	v0003246 - STRONGBUILT CONSTRUCTION	18.97
672	nystrom-NV165	Work Complete	OTHER	234MWS door	10/17/2013	10/17/2013	10/17/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
673	friend-FM234	Work Complete	PLUMBING	623 S37 heat	10/17/2013	10/17/2013	10/18/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
674	hacienda-HA104	Work Complete		HA104 bulbs	10/18/2013	10/18/2013	10/21/2013	-	3.76
675	friend-FM268	Work Complete	SERVICE	608 Stege mice	10/18/2013	10/18/2013	10/22/2013	v0003068 - OMEGA PEST CONTROL	0
676	friend-FM267	Work Complete	PLUMBING	606 Stege disposal	10/18/2013	10/18/2013	10/18/2013	v0002938 - PREFERRED PLUMBING & DRA	0
677	nystrom-NV107	Work Complete	PLUMBING	1329 Virg. stoppage	10/18/2013	10/18/2013	10/18/2013	v0002938 - PREFERRED PLUMBING & DRA	0
678	nevin-NE601	Work Complete	PLUMBING	NE601 basin stpr	10/18/2013	11/01/2013	11/12/2013	-	2.08

679	nystrom-NV116	Work Complete	PLUMBING	325MWS faucet	10/18/2013	11/04/2013	11/13/2013	v0003246 - STRONGBUILT CONSTRUCTION	19.99
68	nevin-NE101	Work Complete	SERVICE	NE101 glass	07/08/2013	07/08/2013	07/12/2013	v0002940 - ALL GLASS	0
681	hacienda-HA109	Work Complete		HA109 batteries	10/21/2013	10/21/2013	10/21/2013	-	1.25
682	nystrom-NV104	Work Complete	SERVICE	1311 Virg pilots	10/21/2013	10/21/2013	10/23/2013	v0003246 - STRONGBUILT CONSTRUCTION	34.95
683	friend-FM233	Work Complete	PLUMBING	621 S37 flush	10/21/2013	10/21/2013	10/25/2013	-	0
685	friend-FM251	Work Complete		574 Stege stove	10/21/2013	10/21/2013	10/22/2013	-	0
686	nystrom-NV134	Work Complete	OTHER	263 MWS detrash	10/17/2013	10/18/2013	10/18/2013	v0003352 - KJR ENTERPRISES	0
687	friend-	Work Complete	SERVICE	FM gutters	10/17/2013	10/18/2013	10/21/2013	v0003352 - KJR ENTERPRISES	0
688	nystrom-NV186	Work Complete	PLUMBING	267 S16 heat	10/21/2013	10/21/2013	10/22/2013	v0003246 - STRONGBUILT CONSTRUCTION	26.96
691	triangle-TC88	Work Complete	OTHER	966 TC tile	10/21/2013	10/21/2013	10/24/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
692	nevin-NE621	Work Complete	OTHER	NE621 vacant	10/21/2013	10/23/2013	11/04/2013	v0003283 - OAKLAND CONSTRUCTION GR	414.95
693	nevin-NE302	Work Complete	OTHER	NE302 vacant	10/21/2013	10/23/2013	11/04/2013	v0003237 - ALPHA DESIGN PLANNING/CO	478.6
694	hacienda-HA320	Work Complete	OTHER	HA320 vacant	10/21/2013	10/23/2013	11/05/2013	v0003246 - STRONGBUILT CONSTRUCTION	666.08
695	hacienda-HA314	Work Complete	OTHER	HA314 vacant	10/21/2013	10/23/2013	10/28/2013	v0003246 - STRONGBUILT CONSTRUCTION	386.62
696	friend-FM251	Work Complete	OTHER	574 Stege stove	10/22/2013	10/22/2013	10/23/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
697	friend-FM256	Work Complete	OTHER	584 Stege stove	10/22/2013	10/22/2013	10/22/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
699	hacienda-HA203	Work Complete	PLUMBING	HA201 Ceiling leak	10/22/2013	10/23/2013	11/05/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
70	nystrom-NV110	Work Complete	PLUMBING	351 MWS heat	07/08/2013	07/08/2013	07/08/2013	-	0
700	nevin-NE203	Work Complete	OTHER	NE203 refrig.	10/22/2013	10/22/2013	10/23/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
701	triangle-TC33	Work Complete	PLUMBING	938 9th Heater/ water leak	10/22/2013	10/23/2013	11/05/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
703	friend-FM239	Work Complete	PLUMBING	548 Stege heat	10/22/2013	10/22/2013	11/28/2013	v0003246 - STRONGBUILT CONSTRUCTION	26.96
704	nevin-NE212	Work Complete	PLUMBING	NE212 leak	10/23/2013	10/23/2013	10/24/2013	v0003246 - STRONGBUILT CONSTRUCTION	0.91
706	nystrom-NV120	Work Complete	SERVICE	1328 Maine locks	10/24/2013	10/29/2013	10/30/2013	v0002935 - B&B LOCKSMITH	0
709	nevin-NE325	Work Complete	OTHER	NE325 mail key	10/24/2013	10/29/2013	10/29/2013	-	0
710	nystrom-NV133	Work Complete	PLUMBING	1329 Maine Heater	10/24/2013	10/29/2013	10/29/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
711	nystrom-NV121	Work Complete	SERVICE	1324 Maine window	10/25/2013	10/25/2013	10/25/2013	-	0
712	hacienda-HA107	Work Complete	PLUMBING	HA107 stoppage	10/25/2013	10/25/2013	10/26/2013	-	0
713	friend-FM227	Work Complete	PLUMBING	609 S37 stoppage	10/28/2013	10/28/2013	10/28/2013	v0002938 - PREFERRED PLUMBING & DRA	0
715	hacienda-HA412	Work Complete	SERVICE	HA412 roaches	10/28/2013	10/29/2013	11/08/2013	v0003068 - OMEGA PEST CONTROL	0
716	hacienda-HA218	Work Complete	SERVICE	HA218 keys	10/28/2013	10/29/2013	10/29/2013	-	0
717	nystrom-NV178	Work Complete	PLUMBING	251 S15 heater	10/28/2013	10/29/2013	11/09/2013	v0003046 - ROBINSON	27.43
719	friend-	Work Complete	PLUMBING	568 S37 heater	10/28/2013	10/30/2013	10/30/2013	v0003046 - ROBINSON	26.96

721	nystrom-NV160	Work Complete	PLUMBING	208MWS stoppage	10/29/2013	10/29/2013	10/29/2013	v0002938 - PREFERRED PLUMBING & DRA	0
722	nystrom-NV121	Work Complete	SERVICE	1324 Maine locks	10/08/2013	10/29/2013	10/29/2013	v0002935 - B&B LOCKMSMITH	0
724	hacienda-HA513	Work Complete	PLUMBING	HA513 leak	10/29/2013	10/29/2013	11/25/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
725	nystrom-NV148	Work Complete	PLUMBING	1316 Florida leak	10/29/2013	10/29/2013	11/09/2013	-	0
727	triangle-	Work Complete	OTHER	TC janitorial	10/29/2013	10/29/2013	10/29/2013	-	309.55
728	hacienda-	Work Complete	OTHER	HA janitorial	10/28/2013	10/28/2013	10/28/2013	-	561.18
729	nevin-	Work Complete	OTHER	NE janitorial	10/28/2013	10/28/2013	10/28/2013	-	627.43
730	friend-	Work Complete	OTHER	FM janitorial	10/28/2013	10/28/2013	10/28/2013	-	210.56
733	triangle-TC24	Work Complete	PLUMBING	937 9th stat	10/29/2013	10/29/2013	11/08/2013	-	1.3
735	nevin-	Work Complete	SERVICE	NE TV lock	10/29/2013	10/29/2013	11/05/2013	v0002935 - B&B LOCKMSMITH	0
737	hacienda-HA314	Work Complete	SERVICE	HA314 vlocks	10/29/2013	10/29/2013	11/05/2013	v0002935 - B&B LOCKMSMITH	0
74	triangle-TC61	Work Complete	PLUMBING	959 9th Heat	07/08/2013	07/08/2013	07/23/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
741	triangle-TC89	Work Complete	SERVICE	964 TC roaches	10/30/2013	10/30/2013	11/08/2013	v0003068 - OMEGA PEST CONTROL	0
745	hacienda-HA209	Work Complete	ELECTRICAL	HA209 heat lamp	10/30/2013	10/31/2013	11/08/2013	-	3.21
746	hacienda-HA423	Work Complete	PLUMBING	HA423 leak	10/30/2013	11/04/2013	11/05/2013	v0003246 - STRONGBUILT CONSTRUCTION	2.66
749	friend-FM215	Work Complete	PLUMBING	561 S37 heater	10/31/2013	10/31/2013	10/31/2013	v0003237 - ALPHA DESIGN PLANNING/CO	0
751	triangle-TC3	Work Complete	ELECTRICAL	805 L bulbs	10/31/2013	10/31/2013	10/31/2013	-	0.94
752	friend-FM234	Work Complete	SERVICE	623 S37 keys	10/31/2013	11/01/2013	11/01/2013	-	0
753	nevin-NE402	Work Complete	OTHER	NE402 htr/toilet	10/31/2013	11/20/2013	11/20/2013	v0003246 - STRONGBUILT CONSTRUCTION	28
754	triangle-TC6	Work Complete	ELECTRICAL	913 Linc bulb	10/31/2013	11/01/2013	11/04/2013	-	8.79
755	hacienda-HA409	Work Complete	SERVICE	HA409 roaches	11/01/2013	11/01/2013	11/14/2013	v0003068 - OMEGA PEST CONTROL	0
756	triangle-TC97	Work Complete	PLUMBING	946 TC tub	11/01/2013	11/01/2013	11/01/2013	v0002938 - PREFERRED PLUMBING & DRA	0
757	triangle-TC39	Work Complete	SERVICE	944 8th lockout	11/01/2013	11/01/2013	11/01/2013	-	0
758	hacienda-HA211	Work Complete	SERVICE	HA211 roaches	11/04/2013	11/04/2013	11/08/2013	v0003068 - OMEGA PEST CONTROL	0
759	nystrom-NV124	Work Complete	PLUMBING	310 S13th stoppage	11/04/2013	11/05/2013	11/06/2013	v0002938 - PREFERRED PLUMBING & DRA	0
760	hacienda-HA208	Work Complete	SERVICE	HA208 roaches	11/04/2013	11/04/2013	11/08/2013	v0003068 - OMEGA PEST CONTROL	0
761	hacienda-HA410	Work Complete	SERVICE	HA410 locks	11/04/2013	11/04/2013	11/05/2013	v0002935 - B&B LOCKMSMITH	0
763	nystrom-NV131	Work Complete	SERVICE	1317 Maine locks	11/04/2013	11/04/2013	11/08/2013	v0002935 - B&B LOCKMSMITH	0
764	hacienda-HA208	Work Complete	PLUMBING	HA208 toilet	11/04/2013	11/04/2013	11/09/2013	v0003246 - STRONGBUILT CONSTRUCTION	2.66
765	nevin-NE416	Work Complete	PLUMBING	NE416 mold	11/04/2013	11/04/2013	11/04/2013	-	0
766	nevin-NE418	Work Complete	PLUMBING	NE418 stoppage	11/04/2013	11/04/2013	11/05/2013	v0002938 - PREFERRED PLUMBING & DRA	18.96
767	nystrom-NV154	Work Complete	OTHER	219 S15 door	11/05/2013	11/05/2013	11/13/2013	v0003246 - STRONGBUILT CONSTRUCTION	0

768	nevin-NE416	Work Complete	PLUMBING	NE416 shower	11/05/2013	11/05/2013	11/05/2013	v0002938 - PREFERRED PLUMBING & DRA	0
769	nevin-	Work Complete	SERVICE	NE restroom	11/06/2013	11/06/2013	11/06/2013	-	0
774	hacienda-HA605	Work Complete	SERVICE	HA605 roaches	11/06/2013	11/06/2013	11/08/2013	v0003068 - OMEGA PEST CONTROL	0
776	triangle-TC56	Work Complete	ELECTRICAL	921 TC battery	11/06/2013	11/06/2013	11/08/2013	-	2.5
777	triangle-TC95	Work Complete	SERVICE	950 TC mice	11/06/2013	11/06/2013	11/07/2013	-	7.62
778	nevin-	Work Complete	OTHER	ADMIN janitorial	11/06/2013	11/06/2013	11/06/2013	-	141.8
779	nystrom-	Work Complete	SERVICE	Nystrom yard	10/24/2013	10/24/2013	10/25/2013	v0003352 - KJR ENTERPRISES	0
780	hacienda-HA215	Work Complete	SERVICE	HA215 roaches	11/06/2013	11/07/2013	11/08/2013	v0003068 - OMEGA PEST CONTROL	0
781	nystrom-NV171	Work Complete	PLUMBING	268MWS heater not workin	11/06/2013	11/08/2013	11/12/2013	v0003246 - STRONGBUILT CONSTRUCTION	26.96
784	triangle-TC98	Work Complete	OTHER	944 TC mow	11/07/2013	11/09/2013	11/09/2013	-	0
785	hacienda-HA402	Work Complete	ELECTRICAL	HA402 smoke	11/07/2013	11/08/2013	11/12/2013	-	2.5
786	hacienda-HA406	Work Complete	ELECTRICAL	HA406 bulb	11/07/2013	11/08/2013	11/12/2013	-	0.55
787	hacienda-HA217	Work Complete	OTHER	HA217 vacant	11/04/2013	11/04/2013	11/08/2013	v0003246 - STRONGBUILT CONSTRUCTION	403.03
793	triangle-TC79	Work Complete	SERVICE	984 TC locks	11/08/2013	11/08/2013	11/08/2013	v0002935 - B&B LOCKMSMITH	0
794	nystrom-NV171	Work Complete	SERVICE	268 MWS locks	11/06/2013	11/07/2013	11/09/2013	v0002935 - B&B LOCKMSMITH	0
796	hacienda-HA510	Work Complete	OTHER	HA510 ceiling	11/06/2013	11/07/2013	11/09/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
797	nystrom-NV114	Work Complete	OTHER	335 MWS wall	11/01/2013	11/08/2013	11/13/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
798	hacienda-	Work Complete	PLUMBING	HA leak	11/08/2013	11/08/2013	11/12/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
800	friend-FM239	Work Complete	SERVICE	548 Stege locks	10/22/2013	10/24/2013	11/08/2013	v0002935 - B&B LOCKMSMITH	0
801	hacienda-HA211	Work Complete	SERVICE	HA211 locks	10/21/2013	10/22/2013	11/08/2013	v0002935 - B&B LOCKMSMITH	0
802	nystrom-NV131	Work Complete	PLUMBING	1317 Maine drains	11/06/2013	11/06/2013	11/06/2013	v0002938 - PREFERRED PLUMBING & DRA	0
803	nystrom-NV190	Work Complete	PLUMBING	241 S16 stoppage	11/06/2013	11/06/2013	11/06/2013	v0002938 - PREFERRED PLUMBING & DRA	0
804	nystrom-NV191	Work Complete	PLUMBING	233 S16 drains	10/21/2013	10/21/2013	10/22/2013	v0002938 - PREFERRED PLUMBING & DRA	0
805	friend-FM228	Work Complete	PLUMBING	611 S37 stoppage	10/25/2013	10/25/2013	10/25/2013	v0002938 - PREFERRED PLUMBING & DRA	0
806	triangle-	Work Complete	SERVICE	992 TC roaches	10/03/2013	10/03/2013	10/08/2013	-	0
808	nystrom-NV194	Work Complete	PLUMBING	217 S16 heat	11/12/2013	11/12/2013	11/14/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
809	nevin-	Work Complete	SERVICE	Admin office - Roaches	11/12/2013	11/12/2013	11/14/2013	v0003068 - OMEGA PEST CONTROL	0
81	friend-FM216	Work Complete	PLUMBING	563 S37 stoppage	07/08/2013	07/08/2013	07/08/2013	v0002938 - PREFERRED PLUMBING & DRA	0
810	nystrom-NV111	Work Complete	SERVICE	349 MWS lockout	11/12/2013	11/12/2013	11/12/2013	-	0
811	hacienda-HA209	Work Complete	SERVICE	HA209 roaches	11/12/2013	11/12/2013	11/14/2013	v0003068 - OMEGA PEST CONTROL	0
812	nevin-NE727	Work Complete	PLUMBING	NE727 basin	11/12/2013	11/12/2013	11/15/2013	v0003246 - STRONGBUILT CONSTRUCTION	86.86
814	nystrom-NV154	Work Complete	OTHER	219 S15 trash	11/12/2013	11/12/2013	11/12/2013	-	0

815	hacienda-HA213	Work Complete	SERVICE	HA413 roaches	11/12/2013	11/12/2013	11/14/2013	v0003068 - OMEGA PEST CONTROL	0
816	nevin-NE206	Work Complete	OTHER	NE206 cabinet	11/13/2013	11/13/2013	11/20/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
819	nevin-NE206	Work Complete	SERVICE	NE206 roaches	11/13/2013	11/14/2013	11/14/2013	v0003068 - OMEGA PEST CONTROL	0
820	friend-FM221	Work Complete	PLUMBING	577 S37 heat	11/13/2013	11/14/2013	11/15/2013	-	0
822	nevin-NE412	Work Complete	PLUMBING	NE412 Toilet clogged	11/13/2013	11/13/2013	11/13/2013	-	0
825	nystrom-NV154	Work Complete	OTHER	219 S15 rear door	11/13/2013	11/14/2013	11/15/2013	v0003246 - STRONGBUILT CONSTRUCTION	0.41
826	hacienda-	Work Complete	OTHER	HA janitorial	11/13/2013	11/13/2013	11/14/2013	-	273.62
828	triangle-TC62	Work Complete	SERVICE	957 9 roaches	11/14/2013	11/14/2013	11/17/2013	v0003068 - OMEGA PEST CONTROL	0
829	hacienda-HA217	Work Complete	SERVICE	HA217 roaches	11/14/2013	11/14/2013	11/14/2013	v0003068 - OMEGA PEST CONTROL	0
83	friend-FM232	Work Complete	SERVICE	619 37th roaches	07/08/2013	07/08/2013	07/09/2013	v0003068 - OMEGA PEST CONTROL	0
830	friend-	Work Complete	OTHER	FM janitorial	11/14/2013	11/14/2013	11/14/2013	-	9.32
831	hacienda-HA525	Work Complete	SERVICE	HA525 window	11/14/2013	11/14/2013	11/21/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
833	nevin-NE511	Work Complete	ELECTRICAL	NE511 efix	11/14/2013	11/15/2013	11/15/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
834	nevin-NE602	Work Complete	PLUMBING	NE602 flush	11/15/2013	11/15/2013	11/15/2013	-	4.51
836	nystrom-NV122	Work Complete	PLUMBING	1316 Maine stpg	11/18/2013	11/18/2013	11/18/2013	v0002938 - PREFERRED PLUMBING & DRA	0
837	triangle-TC36	Work Complete	SERVICE	915 TC windows	11/18/2013	11/18/2013	11/21/2013	v0002940 - ALL GLASS	0
838	nevin-NE721	Work Complete	ELECTRICAL	NE721 fire	11/18/2013	11/18/2013	11/22/2013	v0003046 - ROBINSON	106.23
842	nystrom-	Work Complete	SERVICE	NV office	11/19/2013	11/19/2013	11/21/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
848	nystrom-NV127	Work Complete	PLUMBING	250 S13 heat	11/19/2013	11/19/2013	11/19/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
849	triangle-TC22	Work Complete	SERVICE	938 8th stove	11/18/2013	11/19/2013	11/19/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
850	nevin-NE403	Work Complete	PLUMBING	NE403 stoppage	11/19/2013	11/19/2013	11/19/2013	v0002938 - PREFERRED PLUMBING & DRA	0
854	hacienda-	Work Complete	ELECTRICAL	HAC elec/boiler	11/18/2013	11/18/2013	11/19/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
855	nevin-	Work Complete	SERVICE	NE gen/rm	11/19/2013	11/19/2013	11/19/2013	v0003246 - STRONGBUILT CONSTRUCTION	4.95
86	friend-	Work Complete	SERVICE	FM gate lock	07/08/2013	07/09/2013	07/09/2013	v0002935 - B&B LOCKSMITH	0
860	hacienda-HA309	Work Complete	SERVICE	HA309 eviction	11/25/2013	11/25/2013	11/26/2013	v0002935 - B&B LOCKSMITH	0
861	nevin-NE412	Work Complete	PLUMBING	NE412 stoppage	11/20/2013	11/20/2013	11/20/2013	v0002938 - PREFERRED PLUMBING & DRA	0
862	nevin-NE401	Work Complete	PLUMBING	NE401 tub	11/19/2013	11/20/2013	11/20/2013	v0003246 - STRONGBUILT CONSTRUCTION	14.45
866	hacienda-HA401	Work Complete	SERVICE	HA401 eviction	11/25/2013	11/25/2013	11/25/2013	v0002935 - B&B LOCKSMITH	0
867	nevin-	Work Complete	PLUMBING	NE admin flood	11/26/2013	11/26/2013	11/26/2013	v0003246 - STRONGBUILT CONSTRUCTION	0
868	triangle-TC30	Work Complete	PLUMBING	932 9th stoppage	11/21/2013	11/21/2013	11/21/2013	v0002938 - PREFERRED PLUMBING & DRA	0
869	hacienda-HA605	Work Complete	SERVICE	HA605 window	11/25/2013	11/26/2013	11/27/2013	v0002940 - ALL GLASS	0
875	hacienda-HA414	Work Complete	PLUMBING	HA414 leak	11/21/2013	11/22/2013	11/22/2013	v0003246 - STRONGBUILT CONSTRUCTION	0

