



ATTACHMENT NO. 3: REMEDIATION ACTIVITIES SUMMARY REPORT

Remediation Activities Conducted

Permit No. 839805
 Investigation Permit No. 761771
 Parcel ID(s): 24-26-18-0060-00000-1070
 Property Address: 21835 Ocean Pines Dr.
Land O Lakes, FL 34639
 Owner(s) Name: Steve and Vaughn Jakubiec
 Date(s) Remediation Conducted: October 9, 2014 to October 15, 2014

Rcpt: 1640437 Rec: 10.00
 DS: 0.00 IT: 0.00
 11/06/14 L. Korb, Dpty Clerk

PAULA S. O'NEIL, Ph.D. PASCO CLERK & COMPROLLER
 11/06/14 12:13pm 1 of 1
 OR BK **9108** PG **1385**

Remediation Activities Conducted:

Compaction grout

Materials, including quantities, used and cost of such materials and labor.

A total of 33 pressure pin piles

Ranging from 38 ft to 59 ft.

Each pin pile was hydraulically driven into the soil until enough pressure was reached for refusal.

Labor: \$2,500.00

Materials: \$27,797.00

Explanation of any differences in remedial activity recommended in Investigation Permit Findings and those conducted:

Permit # 761771 states sinkhole activity the homeowners decided to proceed with the recommended pin piles to repair their home.

Amount of any payment(s) by an insurer to the owner(s) pursuant to a claim for ground settlement on this parcel(s):

\$30,297.00

Number of pages of attachments to this report: 0