

S/H



Corrected

Rcpt: 1882210 Rec: 10.00
DS: 0.00 IT: 0.00
07/26/2017 K. A., Dpty Clerk

ATTACHMENT NO. 3: REMEDIATION ACTIVITIES SUMMARY REPORT

Remediation Activities Conducted

PAULA S. O'NEIL, Ph.D. PASCO CLERK & COMPTROLLER
07/26/2017 01:23pm 1 of 1
OR BK 9579 PG 1551

Permit No. 839805
Investigation Permit No. 761771
Parcel ID(s): 24-26-18-0060-00000-1070
Property Address: 21835 Ocean Pines Dr.
Land O Lakes, FL 34639
Owner (s) Name: Steve and Vaughn Jakubiec
Date(s) Remediation Conducted: October 9,2014 to October 15,2014

Remediation Activities Conducted:

Underpinning

Materials, including quantities, used and cost of such materials and labor:

A total of 33 pressure pin piles

Ranging from 38ft to 59 ft.

Each pin pile was hydraulically driven into the soil until enough pressure was reached for refusal

Labor: \$2,500.00
Materials: \$27,797.00

Explanation of any differences in remedial activity recommended in Investigation Permit Findings and those conducted:

Permit # 761771 states sinkhole activity the homeowners decided to proceed with the recommended pin piles to repair their home.

Amount of any payment(s) by an insurer to the owner(s) pursuant to a claim for ground settlement on this parcel(s):
\$30,297.00

Number of pages of attachments to this report: 0