

LEGAL ID: ON FILE	NO. OF CONST NEW SQ. FT STORIES TYPE OCCUP GROUP STRUCTURE: 432 1 V-B U	BUILDING ADDRESS: 0000 RED BOX RD MT WILSON LCNT CA NEAREST CROSS STREET: THOMAS PAGE: GRID: LOCALITY: MT WILSON
ASSESSOR INFORMATION NUMBER:	EXIST BLDG USE: COMME USE ZONE: X EXIST OCC GRP: U	ISSUED ON: 07/23/18 PROCESSED BY: MM
TENANT:	BLDGS. NOW ON LOT: VALUATION: 52,000	FINAL DATE: 12/19/18 FINAL BY: C. Poz CODE: 5
OWNER: FOX 11 - KTV 1999 S BUNNY DR LOS ANGELES CA	OWNER: TEL. NO: FOX 11 - KTV 1999 S BUNNY DR LOS ANGELES CA	DESCRIPTION OF WORK MASONARY EQUIPMENT STRUCTURE 432 SF
APPLICANT: POINTVIEW TECH LLC	APPLICANT: TEL. NO: POINTVIEW TECH LLC (909) 592-7120-	SPECIAL CONDITIONS:
CONTRACTOR: SEA WEST ENTERPRISES 373 E FOOTHILL BLVD SUITE 200 SAN DIMAS CA 91773	CONTRACTOR: TEL. NO: SEA WEST ENTERPRISES (909) 592-7120- LIC. NO 486074	APPROVALS DATE INSPECTOR SIGNATURE
ARCHITECT OR ENGINEER: HUNT, GLEN 604 FOX GLEN BARRINGTON IL 90010	ARCHITECT OR ENGINEER: TEL. NO: HUNT, GLEN (847) 277-8070- LIC. NO: 67146	LOCATION AND SETBACKS 7/31/18 C. Poz
MAP NO: SEWER MAP BOOK: PAGE: FIRE ZONE: CMP: 4 22	MAP NO: SEWER MAP BOOK: PAGE: FIRE ZONE: CMP: 4 22	SOILS ENGINEER APPROVAL 7/31/18 C. Poz
NO. OF FAMILIES: DWELLING UNITS: APT/COND: STAT CLASS: 0 NO 22	NO. OF FAMILIES: DWELLING UNITS: APT/COND: STAT CLASS: 0 NO 22	FOUNDATION/TRENCH FORMS 7/31/18 C. Poz
AIR QUALITY: NO SCHOOL WITHIN 1000 FEET HAZARDOUS MATERIALS NO	AIR QUALITY: NO SCHOOL WITHIN 1000 FEET HAZARDOUS MATERIALS NO	SLAB/UNDER FLOOR
PERMIT EXPIRES 1 YEAR IF 1) WORK DOES NOT COMMENCE, OR 2) WORK IS SUSPENDED OR ABANDONED, OR 3) FAILS TO OBTAIN CODE REQUIRED INSPECTION	PERMIT EXPIRES 1 YEAR IF 1) WORK DOES NOT COMMENCE, OR 2) WORK IS SUSPENDED OR ABANDONED, OR 3) FAILS TO OBTAIN CODE REQUIRED INSPECTION	RAISED FLOOR FRAMING 8/8/18 L. Crosby C. Poz Masonry Walls UNDER FLOOR INSULATION 8/8/18 L. Crosby C. Poz concrete full height FLOOR SHEATHING
REPORT ID: DPR261	REPORT ID: DPR261	ROOF SHEATHING
ROUTE TO: BS0510	ROUTE TO: BS0510	SHEAR PANELS
		FRAME INSPECTION 10/8/18 C. Poz
		FIRE SPRINKLER HANGERS
		INSULATION/WEATHER STRIP 10/8/18 C. Poz
		INTERIOR LATH/DRYWALL panels 10/25/18 C. Poz
		EXTERIOR LATH
		RATED FLOOR/CEIL ASSEM.
		RATED WALL ASSEMBLIES
		RATED SHAFTS/OPENINGS
		T-BAR CEILINGS
		LOT DRAINAGE 12/19/18 C. Poz



LEGAL ID: ON FILE	NO. OF STORIES	CONST TYPE	NEW OCCUP GROUP	BUILDING ADDRESS: 0000 RED BOX RD MT WILSON LCNT CA NEAREST CROSS STREET: THOMAS PAGE: GRID: LOCALITY: MT WILSON
ASSESSOR INFORMATION NUMBER:	STRUCTURE: 0	1	V-B	U
TENANT:	EXIST BLDG USE: COMME	USE ZONE: X	ISSUED ON: 07/23/18	PROCESSED BY: MM
OWNER: FOX 11 - KTTV 1999 S BUNNY DR LOS ANGELES CA	TEL. NO:	BLDGS. NOW ON LOT:	VALUATION: 40,000	FINAL DATE 12/19/18
APPLICANT: POINTVIEW TECH LLC	TEL. NO: (909) 592-7120-	FEE DESCRIPTION:	QUANTITY:	UOM:
CONTRACTOR: SEA WEST ENTERPRISES 373 E FOOTHILL BLVD SUITE 200 SAN DIMAS CA 91773	TEL. NO: (909) 592-7120- LIC. NO 486074	C1 PLANCHCK W/HC 4 000.00 VAL 644.20 AA BLDG PERMIT ISSUANCE 31.10 AB STATE GREEN BLDG FEE 40000.00 VAL 2.00 AE STRONG MOTION OTHER 40000.00 VAL 11.20 C2 PERMIT WITH INCAP 40000.00 VAL 16.10 08 CERTIF OF CONCUBANCY 11.70 TOTAL FEES 111.30	AMOUNT:	DESCRIPTION OF WORK NEW DETACHED OBSERVATORY #1
ARCHITECT OR ENGINEER: HUNT, GLEN 604 FOX GLEN BARRINGTON IL 90010	TEL. NO: (847) 277-8070- LIC. NO: 67146	APPROVALS		
MAP NO: SEWER MAP BOOK: PAGE: FIRE ZONE: CMP: 0 NO 22	NO. OF FAMILIES: DWELLING UNITS: APT/COND: STAT CLASS: 0 NO 22	DATE INSPECTOR SIGNATURE		
AIR QUALITY: NO	SCHOOL WITHIN 1000 FEET NO	HAZARDOUS MATERIALS NO	LOCATION AND SETBACKS 7/31/18 C Pay	
PERMIT EXPIRES 1 YEAR IF 1) WORK DOES NOT COMMENCE, OR 2) WORK IS SUSPENDED OR ABANDONED, OR 3) FAILS TO OBTAIN CODE REQUIRED INSPECTION	REPORT ID: DPR261			SOILS ENGINEER APPROVAL 7/31/18 C Pay
	ROUTE TO: BS0510			FOUNDATION/TRENCH FORMS 7/31/18 C Pay
				SEAB/UNDER FLOOR Masonry walls 8/18/18 C Pay for L. Crosby
				RAISED FLOOR FRAMING about full height. 8/18/18 C Pay for L. Crosby
				UNDERFLOOR INSULATION
				FLOOR SHEATHING
				ROOF SHEATHING
				SHEAR PANELS
				FRAME INSPECTION 10/8/18 C Pay
				FIRE SPRINKLER HANGERS 10/8/18 C Pay
				INSULATION/WEATHER STRIP
				INTERIOR LATH/DESWALL panels. 10/25/18 C Pay
				EXTERIOR LATH
				RATED FLOOR/CEIL ASSEM.
				RATED WALL ASSEMBLIES
				RATED SHAFTS/OPENINGS
				T-BAR CEILINGS
				LOT DRAINAGE 10/19/18 C Pay



LEGAL ID: ON FILE	NO. OF CONST NEW SQ. FT STORIES TYPE OCCUP GROUP STRUCTURE: 0 1 V-B U	BUILDING ADDRESS: 0000 RED BOX RD MT WILSON LCNT CA NEAREST CROSS STREET: THOMAS PAGE: GRID: LOCALITY: MT WILSON
ASSESSOR INFORMATION NUMBER:	EXIST BLDG USE: COMME USE ZONE: X EXIST OCC GRP: U	ISSUED ON: 07/23/18 PROCESSED BY: MM
TENANT:	BLDGS. NOW ON LOT: VALUATION: 45,000	FINAL DATE: 12/19/18 FINAL BY: CBoz CODE: 5
OWNER: FOX 11 - KTTV 1999 S BUNDY DR LOS ANGELES CA	OWNER TEL. NO:	DESCRIPTION OF WORK NEW DETACHED OBSERVATORY #2
APPLICANT: POINTVIEW TECH LLC	APPLICANT TEL. NO: (909) 592-7120	SPECIAL CONDITIONS:
CONTRACTOR: SEA WEST ENTERPRISES 373 E FOOTHILL BLVD SUITE 200 SAN DIMAS CA 91773	CONTRACTOR TEL. NO: (909) 592-7120- LIC. NO: 486074	APPROVALS DATE INSPECTOR SIGNATURE
ARCHITECT OR ENGINEER: HUNT, GLEN 604 FOX GLEN BARRINGTON IL 90010	ARCHITECT OR ENGINEER TEL. NO: (847) 277-8070- LIC. NO: 67146	LOCATION AND SETBACKS 7/31/18 CBoz
MAP NO: SEWER MAP BOOK: PAGE: FIRE ZONE: CMP: 4 22	NO. OF FAMILIES: DWELLING UNITS: APT/COND: STAT CLASS: 0 NO 22	SOILS ENGINEER APPROVAL 7/31/18 CBoz
AIR QUALITY: SCHOOL WITHIN HAZARDOUS NO 1000 FEET MATERIALS NO NO	PERMIT EXPIRES 1 YEAR IF 1) WORK DOES NOT COMMENCE, OR 2) WORK IS SUSPENDED OR ABANDONED, OR 3) FAILS TO OBTAIN CODE REQUIRED INSPECTION	FOUNDATION/TRENCH FORMS 7/31/18 CBoz
		SLAB/UNDER FLOOR (CAISSONS (4)) 8/10/18 L Crosby / CBoz
		RAISED FLOOR FRAMING
		UNDERFLOOR INSULATION
		FLOOR SHEATHING
		ROOF SHEATHING
		SHEAR PANELS
		FRAME INSPECTION 10/25/18 CBoz
		FIRE SPRINKLER HANGERS
		INSULATION/WEATHER STRIP 10/25/18 CBoz
		INTERIOR LATH/DRYWALL panels 10/25/18 CBoz
		EXTERIOR LATH
		RATED FLOOR/CEIL ASSEM.
		RATED WALL ASSEMBLIES
		RATED SHAFTS/OPENINGS
		T-BAR CEILINGS
		LOT DRAINAGE 10/19/18 CBoz



12/19/18 Received all special inspections Reports + Structural observation Reports CBoz